


# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE5605</b>					
<b>Priority :</b>	Low				
<b>Created By :</b>	Admin - Apurva Vajaria				
<b>Complaint Mob. No. :</b>	7798321220				
<b>Technician Name :</b>	Javed Bhaldar		<b>Technician Mobile :</b>	9082348767	
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	31-05-2022 10:24:06		
<b>Vendor Details :</b>					
<b>Company Name/Client Name :</b>	Armstrong (India) Constructions	<b>Customer's Mobile :</b>	7798321220	<b>Name :</b>	Sanket Sir
<b>Address :</b>					
Mumbai , , , , Maharashtra					
<b>AMC Details :</b>					
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>		
<b>Product Name :</b>	Intercom				
<b>Complain :</b>	intercom issue				
<b>Technician Comment :</b>	one complete login main director cabin complete solved everything working fine and ppm done all line testing done 101 testing ok 102 testing ok 103 testing ok 104 cable cut for rat inside pipe cable 2/3 mtr remove in pipe not posible working this ext. 105 testing ok 106 testing ok 107 testing ok 108 cabling continity not giving intercom point to system level cable not okk line dead 109 testing ok but telephone not properly working 110 testing ok 111 testing ok but phone folty not properly working hook switch problem 112 testing ok 113 testing ok				
<b>Complain Operator :</b>	Desktop - Apurva Vajaria				
<b>Remark :</b>	one complete login main director cabin complete solved everything working fine and ppm done all line testing done 101 testing ok 102 testing ok 103 testing ok 104 cable cut for rat inside pipe cable 2/3 mtr remove in pipe not posible working this ext. 105 testing ok 106 testing ok 107 testing ok 108 cabling continity not giving intercom point to system level cable not okk line dead 109 testing ok but telephone not properly working 110 testing ok 111 testing ok but phone folty not properly working hook switch problem 112 testing ok 113 testing ok				

<b>Status History :</b>	Date Time	Technician Name	Status	Remark	Sign
	31-05-2022 04:01:39	Javed Bhaldar	Completed	one complete login main director cabin complete solved everything working fine and ppm done all line testing done 101 testing ok 102 testing ok 103 testing ok 104 cable cut for rat inside pipe cable 2/3 mtr remove in pipe not possible working this ext. 105 testing ok 106 testing ok 107 testing ok 108 cabling continuity not giving intercom point to system level cable not okk line dead 109 testing ok but telephone not properly working 110 testing ok 111 testing ok but phone folty not properly working hook switch problem 112 testing ok 113 testing ok	
	31-05-2022 10:24:25	Javed Bhaldar	New		-
	31-05-2022 10:24:06	Javed Bhaldar	New		-
<b>Previous Complain History :</b>	Date Time	Technician Name	Remark		
	21-05-2022 10:37:48	Javed Bhaldar	one new multivision camera installation done everything working fine		
	18-04-2022 10:34:42	Prashant Nikalje	ppm done		