

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE6502																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	7798321220																								
Technician Name :	Prashant Nikalje		Technician Mobile :	9664609225																					
Ticket Type :	Complain	Date & Time :	03-10-2022 03:56:04																						
Vendor Details :																									
Company Name/Client Name :	Armstrong (India) Constructions	Customer's Mobile :	7798321220	Name :	Sanket Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	CCTV																								
Complain :	CCTV survey																								
Technician Comment :																									
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	CCTV camera survey done 8 CH DVR 4 wide angle camera some camera shifting need to do																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>03-10-2022 04:14:03</td><td>Prashant Nikalje</td><td>Completed</td><td></td><td>-</td></tr><tr><td>03-10-2022 03:56:52</td><td>Prashant Nikalje</td><td>New</td><td></td><td>-</td></tr><tr><td>03-10-2022 03:56:05</td><td>Prashant Nikalje</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	03-10-2022 04:14:03	Prashant Nikalje	Completed		-	03-10-2022 03:56:52	Prashant Nikalje	New		-	03-10-2022 03:56:05	Prashant Nikalje	New		-
Date Time	Technician Name	Status	Remark	Sign																					
03-10-2022 04:14:03	Prashant Nikalje	Completed		-																					
03-10-2022 03:56:52	Prashant Nikalje	New		-																					
03-10-2022 03:56:05	Prashant Nikalje	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>29-09-2022 11:20:44</td><td>Sonu Kumar</td><td>no work camera is very hight</td></tr><tr><td>31-05-2022 10:24:06</td><td>Javed Bhaldar</td><td>one complete login main director cabin complete solved everything working fine and ppm done all line testing done 101 testing ok 102 testing ok 103 testing ok 104 cable cut for rat inside pipe cable 2/3 mtr remove in pipe not posible working this ext. 105 testing ok 106 testing ok 107 testing ok 108 cabling continity not giving intercom point to system level cable not okk line dead 109 testing ok but telephone not properly working 110 testing ok 111 testing ok but phone folty not properly working hook switch problem 112 testing ok 113 testing ok</td></tr></tbody></table>					Date Time	Technician Name	Remark	29-09-2022 11:20:44	Sonu Kumar	no work camera is very hight	31-05-2022 10:24:06	Javed Bhaldar	one complete login main director cabin complete solved everything working fine and ppm done all line testing done 101 testing ok 102 testing ok 103 testing ok 104 cable cut for rat inside pipe cable 2/3 mtr remove in pipe not posible working this ext. 105 testing ok 106 testing ok 107 testing ok 108 cabling continity not giving intercom point to system level cable not okk line dead 109 testing ok but telephone not properly working 110 testing ok 111 testing ok but phone folty not properly working hook switch problem 112 testing ok 113 testing ok											
Date Time	Technician Name	Remark																							
29-09-2022 11:20:44	Sonu Kumar	no work camera is very hight																							
31-05-2022 10:24:06	Javed Bhaldar	one complete login main director cabin complete solved everything working fine and ppm done all line testing done 101 testing ok 102 testing ok 103 testing ok 104 cable cut for rat inside pipe cable 2/3 mtr remove in pipe not posible working this ext. 105 testing ok 106 testing ok 107 testing ok 108 cabling continity not giving intercom point to system level cable not okk line dead 109 testing ok but telephone not properly working 110 testing ok 111 testing ok but phone folty not properly working hook switch problem 112 testing ok 113 testing ok																							