## Vallabh Enterprises

**Regd. Office** : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE3956 Low **Priority** : **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9049503080 **No. :** Technician Mayur Yadav **Technician Mobile** 8411951301 Name : Complain Date & Time : 02-10-2021 05:40:04 **Ticket Type :** Vendor Details : Allianz Managed Customer's Mobile 9049503080 Satyam Mishra Company Name : Name/Client Name Operation & Services Address : Pune,,,,Maharashtra **AMC Details :** 01-07-2021 12:00:00 Non-Comprehensive Expiry Date : Type : **Product Name :** CCTV **Complain**: 5th floor camera sr no. 1 not working 5th floor camera check camera off when NVR restart and and power on when NVR restart on Technician **Comment** : next day camera connection check CEO room camera check Complain Desktop - Apurva Vajaria **Operator** : **Remark** : 5th floor camera check camera off when NVR restart and and power on when NVR restart on next day camera connection check CEO room camera check **Status History : Date Time Technician Name** Status Remark Sign 02-10-2021 05:49:20 MayurYadav Completed 5th floor camera check Ŵ camera off when NVR restart and and power on when NVR restart on next day camera connection check CEO room camera check 02-10-2021 05:41:13 MayurYadav New 02-10-2021 05:40:04 MayurYadav New **Previous Date Time Technician Name** Remark Complain 02-10-2021 05:40:55 beam detector issue resolved and under observation History : MayurYadav 21-08-2020 04:23:50 YasinShaikh ppm done