




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE3957																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9049503080																								
Technician Name :	Mayur Yadav		Technician Mobile :	8411951301																					
Ticket Type :	Complain	Date & Time :	02-10-2021 05:40:55																						
Vendor Details :																									
Company Name/Client Name :	Allianz Managed Operation & Services	Customer's Mobile :	9049503080	Name :	Satyam Mishra																				
Address :																									
Pune , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-07-2021 12:00:00		Type :	Non-Comprehensive																					
Product Name :	Fire																								
Complain :	Beam detector alignment issue																								
Technician Comment :	beam detector issue resolved and under observation																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	beam detector issue resolved and under observation																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>02-10-2021 05:53:46</td><td>MayurYadav</td><td>Completed</td><td>beam detector issue resolved and under observation</td><td></td></tr><tr><td>02-10-2021 05:41:16</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr><tr><td>02-10-2021 05:40:55</td><td>MayurYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	02-10-2021 05:53:46	MayurYadav	Completed	beam detector issue resolved and under observation		02-10-2021 05:41:16	MayurYadav	New		-	02-10-2021 05:40:55	MayurYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																					
02-10-2021 05:53:46	MayurYadav	Completed	beam detector issue resolved and under observation																						
02-10-2021 05:41:16	MayurYadav	New		-																					
02-10-2021 05:40:55	MayurYadav	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>02-10-2021 05:40:04</td><td>MayurYadav</td><td>5th floor camera check camera off when NVR restart and and power on when NVR restart on next day camera connection check CEO room camera check</td></tr><tr><td>21-08-2020 04:23:50</td><td>YasinShaikh</td><td>ppm done</td></tr></tbody></table>					Date Time	Technician Name	Remark	02-10-2021 05:40:04	MayurYadav	5th floor camera check camera off when NVR restart and and power on when NVR restart on next day camera connection check CEO room camera check	21-08-2020 04:23:50	YasinShaikh	ppm done											
Date Time	Technician Name	Remark																							
02-10-2021 05:40:04	MayurYadav	5th floor camera check camera off when NVR restart and and power on when NVR restart on next day camera connection check CEO room camera check																							
21-08-2020 04:23:50	YasinShaikh	ppm done																							