


Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE2364					
Priority :	Low				
Created By :	Admin - Apurva Vajaria				
Complaint Mob. No. :	9049503080				
Technician Name :	Rishi Desai		Technician Mobile :	8369234074	
Ticket Type :	Complain	Date & Time :	04-12-2020 07:09:04		
Vendor Details :					
Company Name/Client Name :	ALLIANZ TECHNOLOGY SE(PHASE I)	Customer's Mobile :	9049503080	Name :	Satyam Sir
Address :					
Mumbai , , , , Maharashtra					
AMC Details :					
Expiry Date :	30-10-2020 12:00:00		Type :	Comprehensive	
Product Name :	CCTV				
Complain :	2 camera issue 1 hooter issue Intrusion batter issue install 2 hdd - 4 tb fire issue				
Technician Comment :	2 Hdd Changed of 4tb, also replaced 32ch unv NVR , and 2 cp plus camera replaced by new one. one hooter issue resolved and also in gst panel of 4th floor there was a reset problem in panel so we have added one programming card of gst and installed same in panel for temporary purpose, Jablotron 5th floor lithium ion battery changed in panic switch with new one also 12V battery installed jablotron panel. 4th floor panel battery bus work done.				
Complain Operator :	Desktop - Apurva Vajaria				
Remark :	2 Hdd Changed of 4tb, also replaced 32ch unv NVR , and 2 cp plus camera replaced by new one. one hooter issue resolved and also in gst panel of 4th floor there was a reset problem in panel so we have added one programming card of gst and installed same in panel for temporary purpose, Jablotron 5th floor lithium ion battery changed in panic switch with new one also 12V battery installed jablotron panel. 4th floor panel battery bus work done.				

Status History :	Date Time	Technician Name	Status	Remark	Sign
	07-12-2020 06:07:54	RishiDesai	Completed	2 Hdd Changed of 4th, also replaced 32ch unv NVR , and 2 cp plus camera replaced by new one. one hooter issue resolved and also in gst panel of 4th floor there was a reset problem in panel so we have added one programming card of gst and installed same in panel for temporary purpose, Jablotron 5th floor lithium ion battery changed in panic switxh with new one also 12V battery installed jablotron panel. 4th floor panel battery bus work done.	
	04-12-2020 07:09:18	RishiDesai	New		-
	04-12-2020 07:09:04	RishiDesai	New		-
Previous Complain History :	Date Time		Technician Name		Remark
	07-08-2023 12:36:53		PravinJagade		
	10-06-2023 11:34:43		Siddhesh Chavan		