

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE736																																			
Priority :	High																																		
Created By :	Admin - Apurva Vajaria																																		
Complaint Mob. No. :	2239417700																																		
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																															
Ticket Type :	Complain	Date & Time :	27-11-2019 05:24:02																																
Vendor Details :																																			
Company Name/Client Name :	Beam Hospital (Womens Hospital)	Customer's Mobile :	2239417700	Name :	Shazia																														
Address :																																			
Mumbai , , , , Maharashtra																																			
AMC Details :																																			
Expiry Date :	01-01-1970 05:30:00		Type :																																
Product Name :	Fire																																		
Complain :	1 smoke detector giving false Alarm on 3rd floor																																		
Technician Comment :	3rd floor S. D. faulty bypass from faulty s. d. and all 4 zone working healthy condition and faulty smoke detector take for check and testing.																																		
Complain Operator :	Desktop - Apurva Vajaria																																		
Remark :	3rd floor S. D. faulty bypass from faulty s. d. and all 4 zone working healthy condition and faulty smoke detector take for check and testing.																																		
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>06-12-2019 03:25:05</td><td>Atique Salmani</td><td>Completed</td><td></td><td>-</td></tr><tr><td>02-12-2019 02:54:53</td><td>Atique Salmani</td><td>Awaiting Spares</td><td></td><td>-</td></tr><tr><td>28-11-2019 06:20:42</td><td>Atique Salmani</td><td>In Progress</td><td>3rd floor S. D. faulty bypass from faulty s. d. and all 4 zone working healthy condition and faulty smoke detector take for check and testing.</td><td></td></tr><tr><td>28-11-2019 11:00:29</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>27-11-2019 05:24:03</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	06-12-2019 03:25:05	Atique Salmani	Completed		-	02-12-2019 02:54:53	Atique Salmani	Awaiting Spares		-	28-11-2019 06:20:42	Atique Salmani	In Progress	3rd floor S. D. faulty bypass from faulty s. d. and all 4 zone working healthy condition and faulty smoke detector take for check and testing.		28-11-2019 11:00:29	Atique Salmani	New		-	27-11-2019 05:24:03	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																															
06-12-2019 03:25:05	Atique Salmani	Completed		-																															
02-12-2019 02:54:53	Atique Salmani	Awaiting Spares		-																															
28-11-2019 06:20:42	Atique Salmani	In Progress	3rd floor S. D. faulty bypass from faulty s. d. and all 4 zone working healthy condition and faulty smoke detector take for check and testing.																																
28-11-2019 11:00:29	Atique Salmani	New		-																															
27-11-2019 05:24:03	Atique Salmani	New		-																															
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>01-11-2019 12:19:19</td><td></td><td></td></tr><tr><td>01-11-2019 12:19:19</td><td>AnilYadav</td><td>one camera properly fixed.now working condition now</td></tr></tbody></table>					Date Time	Technician Name	Remark	01-11-2019 12:19:19			01-11-2019 12:19:19	AnilYadav	one camera properly fixed.now working condition now																					
Date Time	Technician Name	Remark																																	
01-11-2019 12:19:19																																			
01-11-2019 12:19:19	AnilYadav	one camera properly fixed.now working condition now																																	