## Vallabh Enterprises

**Regd. Office** : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 Support : | **W** : www.vallabhenterprises.com **E** : vallabhsecure@yahoo.co.in

Service Status Details : VE1187 **Priority** : High **Created By :** Admin - Apurva Vajaria Complaint 9699209987 Mob. No. : Technician Atique Salmani Technician 8080922984 Name : **Mobile** : Complain Date & Time : 20-02-2020 01:39:24 **Ticket Type : Vendor Details :** Customer's Company Shopperstop 9699209987 Shopperstop Name : Name/Client Kasarwadavali, Mobile : Kasarwadavali, Thane (West).Ashok Thane (west).ashok Name : Lokhande Lokh Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** CCTV need to check the recording is showing only for 12 days need to rectify the same and need to **Complain**: check Technician in 32 channel dvr connected only 18 cameras and recording on all 32 cameras and also frame **Comment**: rate and bite rate was high so set on base of on monthe dta storage and also issue in vewing playback auto logout issue resolved working ok other 2dvr data store 33 days. Complain Desktop - Apurva Vajaria **Operator** : **Remark** : in 32 channel dvr connected only 18 cameras and recording on all 32 cameras and also frame rate and bite rate was high so set on base of on monthe dta storage and also issue in vewing playback auto logout issue resolved working ok other 2dvr data store 33 days. **Status History : Date Time Technician Name** Status Remark Sign 24-02-2020 Atique Salmani Completed in 32 channel dvr connected only 18 cameras and recording on all 03:44:52 32 cameras and also frame rate and bite rate was high so set on base of on monthe dta storage and also issue in vewing playback auto logout issue resolved working ok other 2dvr data store 33 days. 24-02-2020 Atique Salmani New 12:07:27 20-02-2020 Atique Salmani New 01:39:32 20-02-2020 Atique Salmani New 01:39:25

Previous Complain History :	Date Time	Technician Name	Remark
	02-12-2019 02:08:44	MahindraPrajapati	one camera faulty need to send for repair camera collected. for.new camera required 120 meter rj6 and 20 meter 2core cable.
	18-11-2019 11:02:24	SachinPawar	no issue found all working fine