

B K Infotech

Regd. Office : B K InfoTech Basement No 003, Dattani Trade Center Near BMC Office Chandavarkar Road, Borivali West Mumbai - 92
Support : | **W :** <http://www.bkinfotech.in>
E : kalpesh@bkinfotech.in

Service Status Details : BK1076																									
Priority :	High																								
Created By :	Admin - Kalpesh Jain																								
Complaint Mob. No. :	9322290928																								
Technician Name :	Manish Dhangar		Technician Mobile :	9136841712																					
Ticket Type :	New Installation	Date & Time :	17-10-2019 10:19:40																						
Vendor Details :																									
Company Name/Client Name :	Shree Sai Corporate Park Premises Co-Op Society	Customer's Mobile :	9322290928	Name :	Shree Sai Corporate Pandeyji																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	camera service cctv																								
Complain :	1 bullet camera install 3.6mm + 6mm																								
Technician Comment :	1 3.6 mm bullet camera install 1 pandji na 1 6. mm bullet camera diya ma laga diya 2 camera chalu ho gaya 1 lift camera Ka trenmiter.reacver 1 adapter pickup																								
Complain Operator :	Desktop - Kalpesh Jain																								
Remark :	1 3.6 mm bullet camera install 1 pandji na 1 6. mm bullet camera diya ma laga diya 2 camera chalu ho gaya 1 lift camera Ka trenmiter.reacver 1 adapter pickup																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>17-10-2019 05:58:42</td><td>Manish Dhangar</td><td>Work Pending</td><td>1 3.6 mm bullet camera install 1 pandji na 1 6. mm bullet camera diya ma laga diya 2 camera chalu ho gaya 1 lift camera Ka trenmiter.reacver 1 adapter pickup</td><td></td></tr><tr><td>17-10-2019 10:19:46</td><td>Manish Dhangar</td><td>New</td><td></td><td>-</td></tr><tr><td>17-10-2019 10:19:41</td><td>Manish Dhangar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	17-10-2019 05:58:42	Manish Dhangar	Work Pending	1 3.6 mm bullet camera install 1 pandji na 1 6. mm bullet camera diya ma laga diya 2 camera chalu ho gaya 1 lift camera Ka trenmiter.reacver 1 adapter pickup		17-10-2019 10:19:46	Manish Dhangar	New		-	17-10-2019 10:19:41	Manish Dhangar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
17-10-2019 05:58:42	Manish Dhangar	Work Pending	1 3.6 mm bullet camera install 1 pandji na 1 6. mm bullet camera diya ma laga diya 2 camera chalu ho gaya 1 lift camera Ka trenmiter.reacver 1 adapter pickup																						
17-10-2019 10:19:46	Manish Dhangar	New		-																					
17-10-2019 10:19:41	Manish Dhangar	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>18-12-2019 01:36:52</td><td>Manish Dhangar</td><td>3 camera wire power wire problem tha sole kar diya camera chalu kar diya all camera working</td></tr><tr><td>19-11-2019 01:49:11</td><td>Manish Dhangar</td><td>1 lift camera Service 1 camera angle shapting</td></tr></tbody></table>					Date Time	Technician Name	Remark	18-12-2019 01:36:52	Manish Dhangar	3 camera wire power wire problem tha sole kar diya camera chalu kar diya all camera working	19-11-2019 01:49:11	Manish Dhangar	1 lift camera Service 1 camera angle shapting											
Date Time	Technician Name	Remark																							
18-12-2019 01:36:52	Manish Dhangar	3 camera wire power wire problem tha sole kar diya camera chalu kar diya all camera working																							
19-11-2019 01:49:11	Manish Dhangar	1 lift camera Service 1 camera angle shapting																							