Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

E : vallabhsecure@yal	100.C0.ln					
Service Status De	tails: VE11316					
Priority:	Low					
Created By:	Admin - Apurva Vajaria					
Complaint Mob.	9819049156					
Technician Name :	Yogesh Desai		Technician:	Mobile 8080922963		
Ticket Type :	Complain	Date & Time :	05-04-2024 12:33:42			
Vendor Details :						
Company Name/Client Name :	Sotex India Pvt Ltd - Turbhe	Customer's Mobile :	9819049150	6	Name :	Shreeram Sir
Address:					-	
Mumbai , , , 4007	705 , Maharashtra					
AMC Details :						
Expiry Date :	01-01-1970 05:30:00		Type:			
Product Name:	CCTV					
Complain:	panel showing battery wiring fault again					
Technician Comment :	Morley fire panel battery has been changed with new ones of 12v 7ah of two nos Panel was showing earlier battery wirng fault now it's ok Panel and battery and battery under observation					
Complain Operator :	Desktop - Apurva Vajaria					
Remark:	Morley fire panel battery has been changed with new ones of 12v 7ah of two nos Panel was showing earlier battery wirng fault now it's ok Panel and battery and battery under observation					
Status History :	Date Time	Technician Name	Status	Remark		Sign
	22-04-2024 10:21:4	8 YogeshDesai	Completed	Morley fire panel battery has been changed with new ones of 12v 7ah of two nos Panel was showing earlier battery wirng fault now it's ok Panel and battery and battery under observation		
	19-04-2024 11:15:5	7 YogeshDesai	New			-
	19-04-2024 11:14:0		New			-
	16-04-2024 10:47:2	6 YogeshDesai	New			-
Previous Complain History :	Date Time	Technician Name	Remark			
	24-04-2024 10:34:2	3 Atique Salmani	Biomax n ivms software download in sandip sir pc and locally view ok but dvr date n time issue so changed c moss battery dvr on but mouse n vga output issue so collect dvr for check .			
			uvi oli but illo	iuse ii vya oi	utput issue so come	ct uvi ioi check.