







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE41																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9822886000																								
Technician Name :	Yasin Shaikh		Technician Mobile :	8689802313																					
Ticket Type :	Complain	Date & Time :	13-08-2019 06:57:28																						
Vendor Details :																									
Company Name/Client Name :	Patil Builders	Customer's Mobile :	9822886000	Name :	Site																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	CCTV																								
Complain :	1 camera not working and balance camera there is disturbance																								
Technician Comment :	one old camera install and one camera re connection and all camera angle setting done in online hik connect software																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	one old camera install and one camera re connection and all camera angle setting done in online hik connect software																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>27-08-2019 05:24:58</td><td>YasinShaikh</td><td>Completed</td><td>one old camera install and one camera re connection and all camera angle setting done in online hik connect software</td><td></td></tr><tr><td>16-08-2019 04:11:24</td><td>YasinShaikh</td><td>Work Pending</td><td>totally 3cameras off one due to wire cut and removed by client one reconnection and wrking ok and reinstallation painting need drill machine and cameras r so night so need jcb Or ladder something.</td><td></td></tr><tr><td>13-08-2019 06:57:29</td><td>YasinShaikh</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	27-08-2019 05:24:58	YasinShaikh	Completed	one old camera install and one camera re connection and all camera angle setting done in online hik connect software		16-08-2019 04:11:24	YasinShaikh	Work Pending	totally 3cameras off one due to wire cut and removed by client one reconnection and wrking ok and reinstallation painting need drill machine and cameras r so night so need jcb Or ladder something.		13-08-2019 06:57:29	YasinShaikh	New		-
Date Time	Technician Name	Status	Remark	Sign																					
27-08-2019 05:24:58	YasinShaikh	Completed	one old camera install and one camera re connection and all camera angle setting done in online hik connect software																						
16-08-2019 04:11:24	YasinShaikh	Work Pending	totally 3cameras off one due to wire cut and removed by client one reconnection and wrking ok and reinstallation painting need drill machine and cameras r so night so need jcb Or ladder something.																						
13-08-2019 06:57:29	YasinShaikh	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>27-09-2019 11:50:14</td><td></td><td></td></tr><tr><td>06-09-2019 02:16:24</td><td>Sridhar Mandla</td><td>time and date setting done on observation</td></tr></tbody></table>					Date Time	Technician Name	Remark	27-09-2019 11:50:14			06-09-2019 02:16:24	Sridhar Mandla	time and date setting done on observation											
Date Time	Technician Name	Remark																							
27-09-2019 11:50:14																									
06-09-2019 02:16:24	Sridhar Mandla	time and date setting done on observation																							