




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE14719																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9820612503																								
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																					
Ticket Type :	Complain	Date & Time :	13-05-2025 05:23:48																						
Vendor Details :																									
Company Name/Client Name :	Saikripa Auto And Oil Center	Customer's Mobile :	9820612503	Name :	Subhash Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	CCTV																								
Complain :	1)CNG 1 camera some power supply need to give 2)Petrol pump ofc 1 camera getting on off issue 3)CNG DVR mouse not working																								
Technician Comment :	Petrol pump dome camera need to changed 2 time I have changed connectors and one camera petrol pump bullet water insert																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	Petrol pump dome camera need to changed 2 time I have changed connectors and one camera petrol pump bullet water insert																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>13-05-2025 05:59:01</td><td>Atique Salmani</td><td>Completed</td><td></td><td>-</td></tr><tr><td>13-05-2025 05:34:14</td><td>Atique Salmani</td><td>Work Pending</td><td>Petrol pump dome camera need to changed 2 time I have changed connectors and one camera petrol pump bullet water insert</td><td></td></tr><tr><td>13-05-2025 05:28:37</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	13-05-2025 05:59:01	Atique Salmani	Completed		-	13-05-2025 05:34:14	Atique Salmani	Work Pending	Petrol pump dome camera need to changed 2 time I have changed connectors and one camera petrol pump bullet water insert		13-05-2025 05:28:37	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
13-05-2025 05:59:01	Atique Salmani	Completed		-																					
13-05-2025 05:34:14	Atique Salmani	Work Pending	Petrol pump dome camera need to changed 2 time I have changed connectors and one camera petrol pump bullet water insert																						
13-05-2025 05:28:37	Atique Salmani	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>28-07-2025 05:41:59</td><td>Atique Salmani</td><td>There is too much dust inside dvr so blower it and clean it and dvr SMPS exhaust fan not working so it's being heat of supply available then changed .</td></tr><tr><td>26-07-2025 10:38:18</td><td>SantoshPathak</td><td></td></tr></tbody></table>					Date Time	Technician Name	Remark	28-07-2025 05:41:59	Atique Salmani	There is too much dust inside dvr so blower it and clean it and dvr SMPS exhaust fan not working so it's being heat of supply available then changed .	26-07-2025 10:38:18	SantoshPathak												
Date Time	Technician Name	Remark																							
28-07-2025 05:41:59	Atique Salmani	There is too much dust inside dvr so blower it and clean it and dvr SMPS exhaust fan not working so it's being heat of supply available then changed .																							
26-07-2025 10:38:18	SantoshPathak																								