

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE15326																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9820612503																			
Technician Name :	Santosh Pathak		Technician Mobile :	8080922980																
Ticket Type :	New Installation	Date & Time :	21-07-2025 01:49:56																	
Vendor Details :																				
Company Name/Client Name :	Saikripa Auto And Oil Center	Customer's Mobile :	9820612503	Name :	Subhash Sir															
Address :																				
Mumbai , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	Armoud cabling need to do- 100 mtr																			
Technician Comment :																				
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	done by tukaram 53 mtr																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>29-07-2025 02:55:25</td><td>SantoshPathak</td><td>Completed</td><td></td><td>-</td></tr><tr><td>21-07-2025 01:50:44</td><td>SantoshPathak</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	29-07-2025 02:55:25	SantoshPathak	Completed		-	21-07-2025 01:50:44	SantoshPathak	New		-
Date Time	Technician Name	Status	Remark	Sign																
29-07-2025 02:55:25	SantoshPathak	Completed		-																
21-07-2025 01:50:44	SantoshPathak	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>28-07-2025 05:41:59</td><td>Atique Salmani</td><td>There is too much dust inside dvr so blower it and clean it and dvr SMPS exhaust fan not working so it's being heat of supply available then changed .</td></tr><tr><td>26-07-2025 10:38:18</td><td>SantoshPathak</td><td></td></tr></tbody></table>					Date Time	Technician Name	Remark	28-07-2025 05:41:59	Atique Salmani	There is too much dust inside dvr so blower it and clean it and dvr SMPS exhaust fan not working so it's being heat of supply available then changed .	26-07-2025 10:38:18	SantoshPathak							
Date Time	Technician Name	Remark																		
28-07-2025 05:41:59	Atique Salmani	There is too much dust inside dvr so blower it and clean it and dvr SMPS exhaust fan not working so it's being heat of supply available then changed .																		
26-07-2025 10:38:18	SantoshPathak																			