



Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE15357					
Priority :	Low				
Created By :	Admin - Apurva Vajaria				
Complaint Mob. No. :	9820612503				
Technician Name :	Atique Salmani		Technician Mobile :	8080922984	
Ticket Type :	Complain	Date & Time :	24-07-2025 03:29:06		
Vendor Details :					
Company Name/Client Name :	Saikripa Auto And Oil Center	Customer's Mobile :	9820612503	Name :	Subhash Sir
Address :					
Mumbai , , , , Maharashtra					
AMC Details :					
Expiry Date :	01-01-1970 05:30:00		Type :		
Product Name :	CCTV				
Complain :	1)DVR end cameras connection need to do 2)CNG 2 camera off issue 3)Petrol pump ofc mouse not working				
Technician Comment :	4 camera connection done working ok now cng dvr only 16 cameras connect and working c moss new battery changed becz date n time issue milestone usb extender also cable need to rechek painding .				
Complain Operator :	Desktop - Apurva Vajaria				
Remark :	4 camera connection done working ok now cng dvr only 16 cameras connect and working c moss new battery changed becz date n time issue milestone usb extender also cable need to rechek painding .				
Status History :	Date Time	Technician Name	Status	Remark	Sign
	24-07-2025 06:04:41	Atique Salmani	Completed	4 camera connection done working ok now cng dvr only 16 cameras connect and working c moss new battery changed becz date n time issue milestone usb extender also cable need to rechek painding .	
	24-07-2025 06:04:41	Atique Salmani	Completed	4 camera connection done working ok now cng dvr only 16 cameras connect and working c moss new battery changed becz date n time issue milestone usb extender also cable need to rechek painding .	
	24-07-2025 03:29:11	Atique Salmani	New		-

Previous Complain History :	Date Time	Technician Name	Remark
	28-07-2025 05:41:59	Atique Salmani	There is too much dust inside dvr so blower it and clean it and dvr SMPS exhaust fan not working so it's being heat of supply available then changed .
	26-07-2025 10:38:18	SantoshPathak	