







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE15402																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9820612503																								
Technician Name :	Atique Salmani		Technician Mobile :	8080922984																					
Ticket Type :	Complain	Date & Time :	28-07-2025 05:41:59																						
Vendor Details :																									
Company Name/Client Name :	Saikripa Auto And Oil Center	Customer's Mobile :	9820612503	Name :	Subhash Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	CCTV																								
Complain :	cng dvr Getting on off issue																								
Technician Comment :	There is toochh dust inside dvr so blower it and clean it and dvr SMPS exhaust fan not working so it's being heat of supply available then changed .																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	There is toochh dust inside dvr so blower it and clean it and dvr SMPS exhaust fan not working so it's being heat of supply available then changed .																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>28-07-2025 06:07:12</td><td>Atique Salmani</td><td>Completed</td><td>There is toochh dust inside dvr so blower it and clean it and dvr SMPS exhaust fan not working so it's being heat of supply available then changed .</td><td></td></tr><tr><td>28-07-2025 06:07:12</td><td>Atique Salmani</td><td>Completed</td><td>There is toochh dust inside dvr so blower it and clean it and dvr SMPS exhaust fan not working so it's being heat of supply available then changed .</td><td></td></tr><tr><td>28-07-2025 05:42:08</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	28-07-2025 06:07:12	Atique Salmani	Completed	There is toochh dust inside dvr so blower it and clean it and dvr SMPS exhaust fan not working so it's being heat of supply available then changed .		28-07-2025 06:07:12	Atique Salmani	Completed	There is toochh dust inside dvr so blower it and clean it and dvr SMPS exhaust fan not working so it's being heat of supply available then changed .		28-07-2025 05:42:08	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
28-07-2025 06:07:12	Atique Salmani	Completed	There is toochh dust inside dvr so blower it and clean it and dvr SMPS exhaust fan not working so it's being heat of supply available then changed .																						
28-07-2025 06:07:12	Atique Salmani	Completed	There is toochh dust inside dvr so blower it and clean it and dvr SMPS exhaust fan not working so it's being heat of supply available then changed .																						
28-07-2025 05:42:08	Atique Salmani	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>26-07-2025 10:38:18</td><td>SantoshPathak</td><td></td></tr><tr><td>25-07-2025 12:09:03</td><td>Atique Salmani</td><td>Malad petrol pump 7.8 pair faulty swap cable but it's not working cable need to changed 100 150 metr approx</td></tr></tbody></table>					Date Time	Technician Name	Remark	26-07-2025 10:38:18	SantoshPathak		25-07-2025 12:09:03	Atique Salmani	Malad petrol pump 7.8 pair faulty swap cable but it's not working cable need to changed 100 150 metr approx											
Date Time	Technician Name	Remark																							
26-07-2025 10:38:18	SantoshPathak																								
25-07-2025 12:09:03	Atique Salmani	Malad petrol pump 7.8 pair faulty swap cable but it's not working cable need to changed 100 150 metr approx																							