




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE10717																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9820577881																			
Technician Name :	Neeraj Chauhan		Technician Mobile :	8898885764																
Ticket Type :	AMC visiting	Date & Time :	31-01-2024 03:26:20																	
Vendor Details :																				
Company Name/Client Name :	Manglik Co Op Hsg Society Ltd	Customer's Mobile :	9820577881	Name :	Suhas Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	Ppm																			
Complain :	CCTV/Intercom ppm need to do																			
Technician Comment :	Ppm done 1 entry camera breket damage and entercome complaint solved 1- 801 ok 2- 701 phone ringer issue 3- 702 ok 4- 501 phone damage 5 - 502 phone ring not working problem solve new phone install 6- lift phone ringer issue																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	Ppm done 1 entry camera breket damage and entercome complaint solved 1- 801 ok 2- 701 phone ringer issue 3- 702 ok 4- 501 phone damage 5 - 502 phone ring not working problem solve new phone install 6- lift phone ringer issue																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>09-02-2024 03:29:54</td><td>Neeraj Chauhan</td><td>Completed</td><td>Ppm done 1 entry camera breket damage and entercome complaint solved 1- 801 ok 2- 701 phone ringer issue 3- 702 ok 4- 501 phone damage 5 - 502 phone ring not working problem solve new phone install 6- lift phone ringer issue</td><td></td></tr><tr><td>09-02-2024 10:53:47</td><td>Neeraj Chauhan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	09-02-2024 03:29:54	Neeraj Chauhan	Completed	Ppm done 1 entry camera breket damage and entercome complaint solved 1- 801 ok 2- 701 phone ringer issue 3- 702 ok 4- 501 phone damage 5 - 502 phone ring not working problem solve new phone install 6- lift phone ringer issue		09-02-2024 10:53:47	Neeraj Chauhan	New		-
Date Time	Technician Name	Status	Remark	Sign																
09-02-2024 03:29:54	Neeraj Chauhan	Completed	Ppm done 1 entry camera breket damage and entercome complaint solved 1- 801 ok 2- 701 phone ringer issue 3- 702 ok 4- 501 phone damage 5 - 502 phone ring not working problem solve new phone install 6- lift phone ringer issue																	
09-02-2024 10:53:47	Neeraj Chauhan	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>09-01-2024 06:52:08</td><td>Ravi Rajbhar</td><td>subhah sir home 303 intercom line distribution issue resolved and ok working done and chqe collatt</td></tr><tr><td>07-12-2023 12:50:33</td><td>Siddhesh Chavan</td><td>2lift line ok phone ringer issue 302 working OK 303 line distance issue resoved 502 line OK phone ringer issue 503 working OK</td></tr></tbody></table>					Date Time	Technician Name	Remark	09-01-2024 06:52:08	Ravi Rajbhar	subhah sir home 303 intercom line distribution issue resolved and ok working done and chqe collatt	07-12-2023 12:50:33	Siddhesh Chavan	2lift line ok phone ringer issue 302 working OK 303 line distance issue resoved 502 line OK phone ringer issue 503 working OK						
Date Time	Technician Name	Remark																		
09-01-2024 06:52:08	Ravi Rajbhar	subhah sir home 303 intercom line distribution issue resolved and ok working done and chqe collatt																		
07-12-2023 12:50:33	Siddhesh Chavan	2lift line ok phone ringer issue 302 working OK 303 line distance issue resoved 502 line OK phone ringer issue 503 working OK																		