




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE2534</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9820577881																								
<b>Technician Name :</b>	Ravi Rajbhar		<b>Technician Mobile :</b>	8080922965																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	05-01-2021 10:34:24																						
<b>Vendor Details :</b>																									
<b>Company Name/Client Name :</b>	Manglik Co Op Hsg Society Ltd	<b>Customer's Mobile :</b>	9820577881	<b>Name :</b>	Suhas Sir																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>																						
<b>Product Name :</b>	Intercom																								
<b>Complain :</b>	some flats intercom issue																								
<b>Technician Comment :</b>	swap port number 003 and make 1001 line ok instrument issue need to changed and boath lift and also security instrument need to changed .																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	swap port number 003 and make 1001 line ok instrument issue need to changed and boath lift and also security instrument need to changed .																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>05-01-2021 02:01:12</td><td>Ravi Rajbhar</td><td>Completed</td><td>swap port number 003 and make 1001 line ok instrument issue need to changed and boath lift and also security instrument need to changed .</td><td></td></tr><tr><td>05-01-2021 10:34:38</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>05-01-2021 10:34:24</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	05-01-2021 02:01:12	Ravi Rajbhar	Completed	swap port number 003 and make 1001 line ok instrument issue need to changed and boath lift and also security instrument need to changed .		05-01-2021 10:34:38	Ravi Rajbhar	New		-	05-01-2021 10:34:24	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
05-01-2021 02:01:12	Ravi Rajbhar	Completed	swap port number 003 and make 1001 line ok instrument issue need to changed and boath lift and also security instrument need to changed .																						
05-01-2021 10:34:38	Ravi Rajbhar	New		-																					
05-01-2021 10:34:24	Ravi Rajbhar	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>07-08-2023 11:09:33</td><td>ChandanYadav</td><td>303 intercom complain solve and 2 camera angle sitting.</td></tr><tr><td>29-07-2023 01:25:15</td><td>Ravi Rajbhar</td><td>202 ok working 303 ok working 501 line ok instument issue 502 duct side cable tepunching then ok working 701 door lock 903 ok working 1003 ok working and cctv system rcoding playback checking one day 30/7/23</td></tr></tbody></table>					Date Time	Technician Name	Remark	07-08-2023 11:09:33	ChandanYadav	303 intercom complain solve and 2 camera angle sitting.	29-07-2023 01:25:15	Ravi Rajbhar	202 ok working 303 ok working 501 line ok instument issue 502 duct side cable tepunching then ok working 701 door lock 903 ok working 1003 ok working and cctv system rcoding playback checking one day 30/7/23											
Date Time	Technician Name	Remark																							
07-08-2023 11:09:33	ChandanYadav	303 intercom complain solve and 2 camera angle sitting.																							
29-07-2023 01:25:15	Ravi Rajbhar	202 ok working 303 ok working 501 line ok instument issue 502 duct side cable tepunching then ok working 701 door lock 903 ok working 1003 ok working and cctv system rcoding playback checking one day 30/7/23																							