




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE6701</b>																				
<b>Priority :</b>	Low																			
<b>Created By :</b>	Admin - Apurva Vajaria																			
<b>Complaint Mob. No. :</b>	9820577881																			
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984																
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	31-10-2022 10:54:52																	
<b>Vendor Details :</b>																				
Company Name/Client Name :	Manglik Co Op Hsg Society Ltd	Customer's Mobile :	9820577881	Name :	Suhas Sir															
<b>Address :</b>																				
Mumbai , , , , Maharashtra																				
<b>AMC Details :</b>																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
<b>Product Name :</b>	Intercom																			
<b>Complain :</b>	ground to 8th floor cabling need to do																			
<b>Technician Comment :</b>	boath lift cable trace and working ok 1st lift was faulty according to siddesh but we checked it's cable ok green and brown boath pair ok now working ok green pair . and 902 phone issue need to changed and 502 also checked working ok.																			
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																			
<b>Remark :</b>	boath lift cable trace and working ok 1st lift was faulty according to siddesh but we checked it's cable ok green and brown boath pair ok now working ok green pair . and 902 phone issue need to changed and 502 also checked working ok.																			
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>31-10-2022 01:12:26</td><td>Atique Salmani</td><td>Completed</td><td>boath lift cable trace and working ok 1st lift was faulty according to siddesh but we checked it's cable ok green and brown boath pair ok now working ok green pair . and 902 phone issue need to changed and 502 also checked working ok.</td><td></td></tr><tr><td>31-10-2022 10:54:58</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	31-10-2022 01:12:26	Atique Salmani	Completed	boath lift cable trace and working ok 1st lift was faulty according to siddesh but we checked it's cable ok green and brown boath pair ok now working ok green pair . and 902 phone issue need to changed and 502 also checked working ok.		31-10-2022 10:54:58	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																
31-10-2022 01:12:26	Atique Salmani	Completed	boath lift cable trace and working ok 1st lift was faulty according to siddesh but we checked it's cable ok green and brown boath pair ok now working ok green pair . and 902 phone issue need to changed and 502 also checked working ok.																	
31-10-2022 10:54:58	Atique Salmani	New		-																
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>14-10-2022 03:12:00</td><td>Pravin Jagade</td><td>all camera working done. dvr side clin and dressing.</td></tr><tr><td>12-10-2022 11:42:59</td><td>Siddhesh Chavan</td><td>lift phone ok ground to 8 th floor line working cable issue need to change cable and 60 MTR cat 6 cable</td></tr></tbody></table>					Date Time	Technician Name	Remark	14-10-2022 03:12:00	Pravin Jagade	all camera working done. dvr side clin and dressing.	12-10-2022 11:42:59	Siddhesh Chavan	lift phone ok ground to 8 th floor line working cable issue need to change cable and 60 MTR cat 6 cable						
Date Time	Technician Name	Remark																		
14-10-2022 03:12:00	Pravin Jagade	all camera working done. dvr side clin and dressing.																		
12-10-2022 11:42:59	Siddhesh Chavan	lift phone ok ground to 8 th floor line working cable issue need to change cable and 60 MTR cat 6 cable																		