




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE3237</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9137770968																								
<b>Technician Name :</b>	Ravi Rajbhar		<b>Technician Mobile :</b>	8080922965																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	14-06-2021 12:52:06																						
<b>Vendor Details :</b>																									
<b>Company Name/Client Name :</b>	Mandar Pushpa	<b>Customer's Mobile :</b>	9137770968	<b>Name :</b>	Sujata Madam																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
<b>Expiry Date :</b>	30-06-2021 12:00:00		<b>Type :</b>	Non-Comprehensive																					
<b>Product Name :</b>	VDP																								
<b>Complain :</b>	301 901 702 vdp issue																								
<b>Technician Comment :</b>	901 out door camera issue with collat check office 702 ok working also only ringing issue and both side RJ 45 connector change 301 issue resolved main door exit switch issue resolved																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	901 out door camera issue with collat check office 702 ok working also only ringing issue and both side RJ 45 connector change 301 issue resolved main door exit switch issue resolved																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>14-06-2021 02:36:52</td><td>Ravi Rajbhar</td><td>Completed</td><td>901 out door camera issue with collat check office 702 ok working also only ringing issue and both side RJ 45 connector change 301 issue resolved main door exit switch issue resolved</td><td></td></tr><tr><td>14-06-2021 12:52:36</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>14-06-2021 12:52:06</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	14-06-2021 02:36:52	Ravi Rajbhar	Completed	901 out door camera issue with collat check office 702 ok working also only ringing issue and both side RJ 45 connector change 301 issue resolved main door exit switch issue resolved		14-06-2021 12:52:36	Ravi Rajbhar	New		-	14-06-2021 12:52:06	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
14-06-2021 02:36:52	Ravi Rajbhar	Completed	901 out door camera issue with collat check office 702 ok working also only ringing issue and both side RJ 45 connector change 301 issue resolved main door exit switch issue resolved																						
14-06-2021 12:52:36	Ravi Rajbhar	New		-																					
14-06-2021 12:52:06	Ravi Rajbhar	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>29-07-2023 02:15:57</td><td>PravinJagade</td><td>701 continue bell off. Date and time set. Work complete</td></tr><tr><td>29-07-2023 02:14:09</td><td>PravinJagade</td><td></td></tr></tbody></table>					Date Time	Technician Name	Remark	29-07-2023 02:15:57	PravinJagade	701 continue bell off. Date and time set. Work complete	29-07-2023 02:14:09	PravinJagade												
Date Time	Technician Name	Remark																							
29-07-2023 02:15:57	PravinJagade	701 continue bell off. Date and time set. Work complete																							
29-07-2023 02:14:09	PravinJagade																								