

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE13009																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9769141241																			
Technician Name :	Chandan Yadav		Technician Mobile :	9833262842																
Ticket Type :	Complain	Date & Time :	16-10-2024 11:20:36																	
Vendor Details :																				
Company Name/Client Name :	Suman Tower	Customer's Mobile :	9769141241	Name :	Suman Tower Account															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	c wing backside camera need to change																			
Technician Comment :	C wing back side camera working this side new camera install.c wing front side off ieesu solve. Office intercom problem solve.																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	C wing back side camera working this side new camera install.c wing front side off ieesu solve. Office intercom problem solve.																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>16-10-2024 02:58:15</td><td>ChandanYadav</td><td>Completed</td><td>C wing back side camera working this side new camera install.c wing front side off ieesu solve. Office intercom problem solve.</td><td></td></tr><tr><td>16-10-2024 11:20:43</td><td>ChandanYadav</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	16-10-2024 02:58:15	ChandanYadav	Completed	C wing back side camera working this side new camera install.c wing front side off ieesu solve. Office intercom problem solve.		16-10-2024 11:20:43	ChandanYadav	New		-
Date Time	Technician Name	Status	Remark	Sign																
16-10-2024 02:58:15	ChandanYadav	Completed	C wing back side camera working this side new camera install.c wing front side off ieesu solve. Office intercom problem solve.																	
16-10-2024 11:20:43	ChandanYadav	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>27-09-2024 10:19:51</td><td>Ravi Rajbhar</td><td>suman tower flat no. 101 intercom issue resolved and ok working done</td></tr><tr><td>23-09-2024 11:29:45</td><td>ChandanYadav</td><td></td></tr></tbody></table>					Date Time	Technician Name	Remark	27-09-2024 10:19:51	Ravi Rajbhar	suman tower flat no. 101 intercom issue resolved and ok working done	23-09-2024 11:29:45	ChandanYadav							
Date Time	Technician Name	Remark																		
27-09-2024 10:19:51	Ravi Rajbhar	suman tower flat no. 101 intercom issue resolved and ok working done																		
23-09-2024 11:29:45	ChandanYadav																			