




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE14761</b>																																								
<b>Priority :</b>	Low																																							
<b>Created By :</b>	Admin - Apurva Vajaria																																							
<b>Complaint Mob. No. :</b>	9113346616																																							
<b>Technician Name :</b>	Siddhesh Chavan		<b>Technician Mobile :</b>	8080922985																																				
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	19-05-2025 12:21:56																																					
<b>Vendor Details :</b>																																								
Company Name/Client Name :	Vasant Villa CHS	Customer's Mobile :	9113346616	Name :	Suraj Sir																																			
<b>Address :</b>																																								
Mumbai , , , , Maharashtra																																								
<b>AMC Details :</b>																																								
Expiry Date :	31-03-2021 12:00:00		Type :	Non-Comprehensive																																				
<b>Product Name :</b>	VDP																																							
<b>Complain :</b>	flat no. 15 bell press 17/18 also bell ring																																							
<b>Technician Comment :</b>	Some come blurr so changed bit rate and resolution and keep on under observation cameras working ok.																																							
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																																							
<b>Remark :</b>	Some come blurr so changed bit rate and resolution and keep on under observation cameras working ok.																																							
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>14-06-2025 01:08:48</td><td>Siddhesh Chavan</td><td>Completed</td><td></td><td>-</td></tr><tr><td>23-05-2025 10:58:04</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>20-05-2025 03:48:17</td><td>Siddhesh Chavan</td><td>Work Pending</td><td></td><td>-</td></tr><tr><td>20-05-2025 03:41:07</td><td>Siddhesh Chavan</td><td>Completed</td><td>Some come blurr so changed bit rate and resolution and keep on under observation cameras working ok.</td><td></td></tr><tr><td>19-05-2025 04:18:47</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr><tr><td>19-05-2025 12:22:06</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	14-06-2025 01:08:48	Siddhesh Chavan	Completed		-	23-05-2025 10:58:04	Siddhesh Chavan	New		-	20-05-2025 03:48:17	Siddhesh Chavan	Work Pending		-	20-05-2025 03:41:07	Siddhesh Chavan	Completed	Some come blurr so changed bit rate and resolution and keep on under observation cameras working ok.		19-05-2025 04:18:47	Siddhesh Chavan	New		-	19-05-2025 12:22:06	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																																				
14-06-2025 01:08:48	Siddhesh Chavan	Completed		-																																				
23-05-2025 10:58:04	Siddhesh Chavan	New		-																																				
20-05-2025 03:48:17	Siddhesh Chavan	Work Pending		-																																				
20-05-2025 03:41:07	Siddhesh Chavan	Completed	Some come blurr so changed bit rate and resolution and keep on under observation cameras working ok.																																					
19-05-2025 04:18:47	Siddhesh Chavan	New		-																																				
19-05-2025 12:22:06	Siddhesh Chavan	New		-																																				
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>12-06-2025 10:42:54</td><td>PravinJagade</td><td>98 no intercom issue resolve done. Reception to flat calling proper. Work complete.</td></tr><tr><td>28-05-2025 11:58:42</td><td>PravinJagade</td><td>1)Flat no. 15VDP shot it is continue-ringing issue- 15 flat 2)17 &amp; 18 flat no. VDP ok check out side temprary because out side not power need to duct in side power supply port In evening again visited pravin/prashant and 12V 5AMP Power supply installed issue resolved</td></tr></tbody></table>					Date Time	Technician Name	Remark	12-06-2025 10:42:54	PravinJagade	98 no intercom issue resolve done. Reception to flat calling proper. Work complete.	28-05-2025 11:58:42	PravinJagade	1)Flat no. 15VDP shot it is continue-ringing issue- 15 flat 2)17 & 18 flat no. VDP ok check out side temprary because out side not power need to duct in side power supply port In evening again visited pravin/prashant and 12V 5AMP Power supply installed issue resolved																										
Date Time	Technician Name	Remark																																						
12-06-2025 10:42:54	PravinJagade	98 no intercom issue resolve done. Reception to flat calling proper. Work complete.																																						
28-05-2025 11:58:42	PravinJagade	1)Flat no. 15VDP shot it is continue-ringing issue- 15 flat 2)17 & 18 flat no. VDP ok check out side temprary because out side not power need to duct in side power supply port In evening again visited pravin/prashant and 12V 5AMP Power supply installed issue resolved																																						