Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE14977 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9113346616 **No. :** Technician Pravin Jagade **Technician Mobile :** 7262044153 Name : Complain 12-06-2025 10:42:54 **Ticket Type :** Date & Time : **Vendor Details :** Company Vasant Villa Customer's Mobile 9113346616 Name : Suraj Sir Name/Client CHS Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 31-03-2021 12:00:00 Non-Comprehensive Expiry Date : Type : **Product Name :** Intercom **Complain**: Reception intercom issue 98 no intercom issue resolve done. Reception to flat calling proper. Work complete. Technician **Comment** : Complain Desktop - Apurva Vajaria **Operator** : **Remark** : 98 no intercom issue resolve done. Reception to flat calling proper. Work complete. **Status History : Technician Name Date Time** Status Remark Sign 12-06-2025 01:42:56 PravinJagade Completed 98 no intercom issue resolve done. Reception to flat calling proper. Work complete. 12-06-2025 10:43:02 PravinJagade New **Previous Date Time Technician Name** Remark Complain History : 28-05-2025 PravinJagade 1)Flat no. 15VDP shot it is continue-ringing issue- 15 flat 2)17 & 18 flat no. VDP ok check out side temprary because out side not 11:58:42 power need to duct in side power supply port In evening again visited pravin/prashant and 12V 5AMP Power supply installed issue resolved 19-05-2025 Siddhesh Chavan Some come blurr so changed bit rate and resolution and keep 12:21:56 on under observation cameras working ok.