

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE15761																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9113346616																								
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																					
Ticket Type :	Call Basis	Date & Time :	10-09-2025 10:09:27																						
Vendor Details :																									
Company Name/Client Name :	Vasant Villa CHS	Customer's Mobile :	9113346616	Name :	Suraj Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	31-03-2021 12:00:00		Type :	Non-Comprehensive																					
Product Name :	Intercom																								
Complain :	reception new caller id phone need to install																								
Technician Comment :	New coller id phone install with data and time set And flat no. 7 complaint resolve And reception required rj 11 puch code with roject box Need to change next time																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	New coller id phone install with data and time set And flat no. 7 complaint resolve And reception required rj 11 puch code with roject box Need to change next time																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>10-09-2025 12:01:51</td><td>Ravi Rajbhar</td><td>Completed</td><td>New coller id phone install with data and time set And flat no. 7 complaint resolve And reception required rj 11 puch code with roject box Need to change next time</td><td>BDYADAL</td></tr><tr><td>10-09-2025 12:01:49</td><td>Ravi Rajbhar</td><td>Completed</td><td>New coller id phone install with data and time set And flat no. 7 complaint resolve And reception required rj 11 puch code with roject box Need to change next time</td><td>RJ</td></tr><tr><td>10-09-2025 10:09:35</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	10-09-2025 12:01:51	Ravi Rajbhar	Completed	New coller id phone install with data and time set And flat no. 7 complaint resolve And reception required rj 11 puch code with roject box Need to change next time	BDYADAL	10-09-2025 12:01:49	Ravi Rajbhar	Completed	New coller id phone install with data and time set And flat no. 7 complaint resolve And reception required rj 11 puch code with roject box Need to change next time	RJ	10-09-2025 10:09:35	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
10-09-2025 12:01:51	Ravi Rajbhar	Completed	New coller id phone install with data and time set And flat no. 7 complaint resolve And reception required rj 11 puch code with roject box Need to change next time	BDYADAL																					
10-09-2025 12:01:49	Ravi Rajbhar	Completed	New coller id phone install with data and time set And flat no. 7 complaint resolve And reception required rj 11 puch code with roject box Need to change next time	RJ																					
10-09-2025 10:09:35	Ravi Rajbhar	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>01-09-2025 05:01:35</td><td>MaroofRaza</td><td>2 new display intercom requirement</td></tr><tr><td>30-07-2025 11:05:55</td><td>MaroofRaza</td><td>Backside camera issue resolved and flat no 10 intercom faulty</td></tr></tbody></table>					Date Time	Technician Name	Remark	01-09-2025 05:01:35	MaroofRaza	2 new display intercom requirement	30-07-2025 11:05:55	MaroofRaza	Backside camera issue resolved and flat no 10 intercom faulty											
Date Time	Technician Name	Remark																							
01-09-2025 05:01:35	MaroofRaza	2 new display intercom requirement																							
30-07-2025 11:05:55	MaroofRaza	Backside camera issue resolved and flat no 10 intercom faulty																							