




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE5510</b>																														
<b>Priority :</b>	Low																													
<b>Created By :</b>	Admin - Apurva Vajaria																													
<b>Complaint Mob. No. :</b>	9819867895																													
<b>Technician Name :</b>	Javed Hanif Bhaldar Bhaldar		<b>Technician Mobile :</b>	9082348767																										
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	20-05-2022 10:28:29																											
<b>Vendor Details :</b>																														
<b>Company Name/Client Name :</b>	Dhavalgiri Co Op Hsg Society Limited	<b>Customer's Mobile :</b>	9819867895	<b>Name :</b>	Suresh Sir																									
<b>Address :</b>																														
Mumbai , , , 400068 , Maharashtra																														
<b>AMC Details :</b>																														
<b>Expiry Date :</b>	30-06-2021 12:00:00		<b>Type :</b>	Comprehensive																										
<b>Product Name :</b>	CCTV																													
<b>Complain :</b>	b wing staircase camera radish in Video																													
<b>Technician Comment :</b>	B wing loby camera problem solved working fine																													
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																													
<b>Remark :</b>	B wing loby camera problem solved working fine																													
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>20-05-2022 02:06:34</td><td>Javed Hanif BhaldarBhaldar</td><td>Completed</td><td>B wing loby camera problem solved working fine</td><td></td></tr><tr><td>20-05-2022 12:03:47</td><td>Javed Hanif BhaldarBhaldar</td><td>New</td><td></td><td>-</td></tr><tr><td>20-05-2022 10:28:43</td><td>Javed Hanif BhaldarBhaldar</td><td>New</td><td></td><td>-</td></tr><tr><td>20-05-2022 10:28:29</td><td>Javed Hanif BhaldarBhaldar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	20-05-2022 02:06:34	Javed Hanif BhaldarBhaldar	Completed	B wing loby camera problem solved working fine		20-05-2022 12:03:47	Javed Hanif BhaldarBhaldar	New		-	20-05-2022 10:28:43	Javed Hanif BhaldarBhaldar	New		-	20-05-2022 10:28:29	Javed Hanif BhaldarBhaldar	New		-
Date Time	Technician Name	Status	Remark	Sign																										
20-05-2022 02:06:34	Javed Hanif BhaldarBhaldar	Completed	B wing loby camera problem solved working fine																											
20-05-2022 12:03:47	Javed Hanif BhaldarBhaldar	New		-																										
20-05-2022 10:28:43	Javed Hanif BhaldarBhaldar	New		-																										
20-05-2022 10:28:29	Javed Hanif BhaldarBhaldar	New		-																										
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>26-04-2022 09:58:35</td><td>Siddhesh Chavan</td><td>one new bullet camera install and working ok</td></tr><tr><td>22-04-2022 10:08:29</td><td>Atique Salmani</td><td>ppm done and one camera issue resolved by changed bnc d c connector and one camerapinkish need to changed and one also blurr need to changed analog camera bullet .</td></tr></tbody></table>					Date Time	Technician Name	Remark	26-04-2022 09:58:35	Siddhesh Chavan	one new bullet camera install and working ok	22-04-2022 10:08:29	Atique Salmani	ppm done and one camera issue resolved by changed bnc d c connector and one camerapinkish need to changed and one also blurr need to changed analog camera bullet .																
Date Time	Technician Name	Remark																												
26-04-2022 09:58:35	Siddhesh Chavan	one new bullet camera install and working ok																												
22-04-2022 10:08:29	Atique Salmani	ppm done and one camera issue resolved by changed bnc d c connector and one camerapinkish need to changed and one also blurr need to changed analog camera bullet .																												