




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | **W :** www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE7348					
Priority :	Low				
Created By :	Admin - Apurva Vajaria				
Complaint Mob. No. :	9821919559				
Technician Name :	Shiva Meena		Technician Mobile :	7489567735	
Ticket Type :	Complain	Date & Time :	12-01-2023 11:32:56		
Vendor Details :					
Company Name/Client Name :	Rahul International School - Boisar	Customer's Mobile :	9821919559	Name :	Sushil Sir - Boisar
Address :					
Mumbai , boisar WEST , , 401501 , Maharashtra					
AMC Details :					
Expiry Date :	01-01-1970 05:30:00		Type :		
Product Name :	CCTV				
Complain :	8 cameras off issue and ground floor admin pc online need to do				
Technician Comment :	Work completed online PC done and dressing complete aal wark complete				
Complain Operator :	Desktop - Apurva Vajaria				
Remark :	Work completed online PC done and dressing complete aal wark complete				

Status History :					
	Date Time	Technician Name	Status	Remark	Sign
	22-02-2023 05:35:04	Shiva Meena	Completed	Work completed online PC done and dressing complete aal work complete	
	22-02-2023 10:26:28	Shiva Meena	New		-
	21-02-2023 06:18:59	Shiva Meena	Work Pending	Admin & principal mobile PC onli6 done Ground floor & 1st floor dressing complete New 2 camera installed 3rd floor Grade 8 & 1st floor passage LHS 1st floor 3 cameras reconnection new balloon use 1st floor all cameras naming done 1st floor new power supply used 6	
	21-02-2023 10:08:35	Shiva Meena	New		-
	20-02-2023 10:13:10	Shiva Meena	New		-
	13-02-2023 06:08:14	Shiva Meena	Work Pending	4 DVR & 2 NVR online done in cvms 2000 & kvms pro desktop software & mobile also 3rd floor DVR all camera naming and angle setting done 1 camera swap 3rd floor cor-ordinater room to 2nd floor Staff room 2nd floor hard disk (HDD) need Tobe changed 3rd floor 8 Channel DVR offline because lan cable not found and 1camera off need to be changed both the cabling Ground. Floor management cabin camera side ballon changed Ground Floor DVR HDD Replaced (office area)	
	13-02-2023 12:34:55	Shiva Meena	New		-
	13-02-2023 10:58:44	Shiva Meena	New		-
	13-01-2023 01:20:35	Shiva Meena	Work Pending		-
	12-01-2023 11:33:33	Shiva Meena	New		-
Previous Complain History :					
	Date Time	Technician Name	Remark		
	28-02-2023 10:19:41	Prashant Nikalje			
	20-02-2023 10:17:31	Shiva Meena	Ppm done and dvr sit dressing 2 floor and 2 floor dressing complete		