




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE8244</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9821919559																								
<b>Technician Name :</b>	Ishwar Meena		<b>Technician Mobile :</b>	9165341500																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	02-05-2023 11:03:34																						
<b>Vendor Details :</b>																									
<b>Company Name/Client Name :</b>	Rahul International School - Boisar	<b>Customer's Mobile :</b>	9821919559	<b>Name :</b>	Sushil Sir - Boisar																				
<b>Address :</b>																									
Mumbai , boisar WEST , , 401501 , Maharashtra																									
<b>AMC Details :</b>																									
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>																						
<b>Product Name :</b>	CCTV																								
<b>Complain :</b>	a wing 1st floor 102 and ground floor assembly room 1 camera off issue also 3rd floor room no 308 camera pinkish issue need to check																								
<b>Technician Comment :</b>	(1) Ground flour office area camera no. 1 issue resolved (2) 1st Floor room no. 102 pinking issue need to be replace with video bloone (3) 3rd floor room no. 308 pinkin issue need to be replace																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	(1) Ground flour office area camera no. 1 issue resolved (2) 1st Floor room no. 102 pinking issue need to be replace with video bloone (3) 3rd floor room no. 308 pinkin issue need to be replace																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>12-05-2023 03:59:19</td><td>Ishwar Meena</td><td>Closed</td><td></td><td>-</td></tr><tr><td>02-05-2023 01:29:14</td><td>Ishwar Meena</td><td>Completed</td><td>(1) Ground flour office area camera no. 1 issue resolved (2) 1st Floor room no. 102 pinking issue need to be replace with video bloone (3) 3rd floor room no. 308 pinkin issue need to be replace</td><td></td></tr><tr><td>02-05-2023 11:03:49</td><td>Ishwar Meena</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	12-05-2023 03:59:19	Ishwar Meena	Closed		-	02-05-2023 01:29:14	Ishwar Meena	Completed	(1) Ground flour office area camera no. 1 issue resolved (2) 1st Floor room no. 102 pinking issue need to be replace with video bloone (3) 3rd floor room no. 308 pinkin issue need to be replace		02-05-2023 11:03:49	Ishwar Meena	New		-
Date Time	Technician Name	Status	Remark	Sign																					
12-05-2023 03:59:19	Ishwar Meena	Closed		-																					
02-05-2023 01:29:14	Ishwar Meena	Completed	(1) Ground flour office area camera no. 1 issue resolved (2) 1st Floor room no. 102 pinking issue need to be replace with video bloone (3) 3rd floor room no. 308 pinkin issue need to be replace																						
02-05-2023 11:03:49	Ishwar Meena	New		-																					

Previous Complain History :	Date Time	Technician Name	Remark
	20-03-2023 10:33:28	PravinJagade	Ground floor dvr beep sound issue resolve. Beep sound off. Dvr setting change. Hdd normal working done. All camera working.
	09-03-2023 02:11:22	Prashant Nikalje	