

# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

Service Status Details : VE12604																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9769755007																			
Technician Name :	Shiva Meena		Technician Mobile :	7489567735																
Ticket Type :	New Installation	Date & Time :	31-08-2024 12:31:26																	
Vendor Details :																				
Company Name/Client Name :	Rahul Degree Collage Miraroad	Customer's Mobile :	9769755007	Name :	Sushil Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	Class no. 103 and 106 new camera need to install																			
Technician Comment :																				
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	Class no. 103 and 106 new camera installation done																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>04-09-2024 12:38:00</td><td>Shiva Meena</td><td>Completed</td><td></td><td>-</td></tr><tr><td>31-08-2024 12:31:59</td><td>Shiva Meena</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	04-09-2024 12:38:00	Shiva Meena	Completed		-	31-08-2024 12:31:59	Shiva Meena	New		-
Date Time	Technician Name	Status	Remark	Sign																
04-09-2024 12:38:00	Shiva Meena	Completed		-																
31-08-2024 12:31:59	Shiva Meena	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>28-08-2024 10:47:57</td><td>Atique Salmani</td><td>C106 camera missing c103 camera missing And one SMPS faulty so changed new SMPS and 1 video baloon Dvr was off due to dvr adaptor issue so give temporary supply from SMPS and working ok .</td></tr><tr><td>06-07-2024 11:12:39</td><td>Ravi Rajbhar</td><td>one cmaera return with install and ok working done and one pair video value used</td></tr></tbody></table>					Date Time	Technician Name	Remark	28-08-2024 10:47:57	Atique Salmani	C106 camera missing c103 camera missing And one SMPS faulty so changed new SMPS and 1 video baloon Dvr was off due to dvr adaptor issue so give temporary supply from SMPS and working ok .	06-07-2024 11:12:39	Ravi Rajbhar	one cmaera return with install and ok working done and one pair video value used						
Date Time	Technician Name	Remark																		
28-08-2024 10:47:57	Atique Salmani	C106 camera missing c103 camera missing And one SMPS faulty so changed new SMPS and 1 video baloon Dvr was off due to dvr adaptor issue so give temporary supply from SMPS and working ok .																		
06-07-2024 11:12:39	Ravi Rajbhar	one cmaera return with install and ok working done and one pair video value used																		