




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE11321					
Priority :	Low				
Created By :	Admin - Apurva Vajaria				
Complaint Mob. No. :	9773740406				
Technician Name :	Anil Yadav		Technician Mobile :	8090436743	
Ticket Type :	Complain	Date & Time :	05-04-2024 05:01:31		
Vendor Details :					
Company Name/Client Name :	Sai Akashdeep Chs Ltd	Customer's Mobile :	9773740406	Name :	Swapnil Sir
Address :					
Mumbai , , , 400064 , Maharashtra					
AMC Details :					
Expiry Date :	30-11-2020 12:00:00		Type :	Non-Comprehensive	
Product Name :	VDP				
Complain :	flat no. 901 VDP lobby cameras not able to view				
Technician Comment :	2nd floor new SMPS installed 4 allready installed 6 new SMPS 8 already installed 10 new SMPS installed 12 new SMPS installed. 14 new installed 16 allready installed 18 new SMPS installed 2201 no screen 2101 adaptor not available 1101 adaptor faulty dead screen 1201 lock 1202 not allowed Paining falte side cheking and duct distributer .				
Complain Operator :	Desktop - Apurva Vajaria				
Remark :	2nd floor new SMPS installed 4 allready installed 6 new SMPS 8 already installed 10 new SMPS installed 12 new SMPS installed. 14 new installed 16 allready installed 18 new SMPS installed 2201 no screen 2101 adaptor not available 1101 adaptor faulty dead screen 1201 lock 1202 not allowed Paining falte side cheking and duct distributer .				

Status History :					
	Date Time	Technician Name	Status	Remark	Sign
	29-04-2024 10:32:41	Anil Yadav	New		-
	26-04-2024 02:07:04	Anil Yadav	New		-
	23-04-2024 07:06:13	Anil Yadav	Work Pending	2nd floor new SMPS installed 4 allready installed 6 new SMPS 8 already installed 10 new SMPS installed 12 new SMPS installed. 14 new installed 16 allready installed 18 new SMPS installed 2201 no screen 2101 adaptor not available 1101 adaptor faulty dead screen 1201 lock 1202 not allowed Painding falte side cheking and duct distributer .	
	23-04-2024 04:44:01	Anil Yadav	New		-
	11-04-2024 04:41:22	Anil Yadav	Work Pending	lobby cmaera viewing issue resolved but need to change power supply 8-10 nos floor duct side with distributor need to change temporary lobby cmaera check our side 2nd and 10th floor lobby camera viewing ok	
	11-04-2024 04:37:20	Anil Yadav	New		-
	11-04-2024 12:46:22	Anil Yadav	New		-
	08-04-2024 02:52:10	Anil Yadav	New		-
	08-04-2024 01:51:34	Anil Yadav	Work Pending	Chekd 2nd floor 1 St vedeo distribution SMPS faulty so changed only for chek but not issue resolved and also swap vedeo distributor from 10 to 2nd floor not issue resolved so remooved our self SMPS and need to recheck cable floor wise up down cable .	
	08-04-2024 09:59:27	Anil Yadav	New		-
	06-04-2024 01:41:46	Anil Yadav	New		-
Previous Complain History :					
	Date Time	Technician Name	Remark		
	26-06-2024 11:44:38	Shiva Meena	Intercom isu solv and ricenecsn done work complete		
	21-06-2024 11:29:43	Neeraj Chauhan	A wing 801 intercom line not found society Office Tv on off issue electric supply issue tv under objarvation		