

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE7997																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9773740406																			
Technician Name :	Santosh Pathak		Technician Mobile :	8080922980																
Ticket Type :	Complain	Date & Time :	29-03-2023 04:48:57																	
Vendor Details :																				
Company Name/Client Name :	Sai Akashdeep Chs Ltd	Customer's Mobile :	9773740406	Name :	Swapnil Sir															
Address :																				
Mumbai , , , 400064 , Maharashtra																				
AMC Details :																				
Expiry Date :	30-11-2020 12:00:00		Type :	Non-Comprehensive																
Product Name :	Intercom																			
Complain :	All flats intercom need to check																			
Technician Comment :																				
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :																				
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>01-04-2023 11:28:19</td><td>SantoshPathak</td><td>New</td><td></td><td>-</td></tr><tr><td>29-03-2023 04:49:06</td><td>SantoshPathak</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	01-04-2023 11:28:19	SantoshPathak	New		-	29-03-2023 04:49:06	SantoshPathak	New		-
Date Time	Technician Name	Status	Remark	Sign																
01-04-2023 11:28:19	SantoshPathak	New		-																
29-03-2023 04:49:06	SantoshPathak	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>31-07-2023 12:33:52</td><td>Ravi Rajbhar</td><td>two camera no video work pending back side gate or east gate and 1601 video door phone lobby camera vieing issue resloved and ok wprking done cable check duct to flat and 2202 intercom cable missing juction side 1901 intercom line ok but phone wall maount and vdp sceen reinstall with cannectoin pending</td></tr><tr><td>15-07-2023 10:29:11</td><td>Kalpesh SubhashGurav</td><td>Old Faulty 4 TB HDD agents new replacement 4 TB HDD Installed Done.</td></tr></tbody></table>					Date Time	Technician Name	Remark	31-07-2023 12:33:52	Ravi Rajbhar	two camera no video work pending back side gate or east gate and 1601 video door phone lobby camera vieing issue resloved and ok wprking done cable check duct to flat and 2202 intercom cable missing juction side 1901 intercom line ok but phone wall maount and vdp sceen reinstall with cannectoin pending	15-07-2023 10:29:11	Kalpesh SubhashGurav	Old Faulty 4 TB HDD agents new replacement 4 TB HDD Installed Done.						
Date Time	Technician Name	Remark																		
31-07-2023 12:33:52	Ravi Rajbhar	two camera no video work pending back side gate or east gate and 1601 video door phone lobby camera vieing issue resloved and ok wprking done cable check duct to flat and 2202 intercom cable missing juction side 1901 intercom line ok but phone wall maount and vdp sceen reinstall with cannectoin pending																		
15-07-2023 10:29:11	Kalpesh SubhashGurav	Old Faulty 4 TB HDD agents new replacement 4 TB HDD Installed Done.																		