

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE8165															
Priority :	Low														
Created By :	Admin - Apurva Vajaria														
Complaint Mob. No. :	9773740406														
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965											
Ticket Type :	Complain	Date & Time :	20-04-2023 11:51:26												
Vendor Details :															
Company Name/Client Name :	Sai Akashdeep Chs Ltd	Customer's Mobile :	9773740406	Name :	Swapnil Sir										
Address :															
Mumbai , , , 400064 , Maharashtra															
AMC Details :															
Expiry Date :	30-11-2020 12:00:00		Type :	Non-Comprehensive											
Product Name :	VDP														
Complain :	402 vdp low voice issue														
Technician Comment :															
Complain Operator :	Desktop - Apurva Vajaria														
Remark :															
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>20-04-2023 11:51:38</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	20-04-2023 11:51:38	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign											
20-04-2023 11:51:38	Ravi Rajbhar	New		-											
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>31-07-2023 12:33:52</td><td>Ravi Rajbhar</td><td>two camera no video work pending back side gate or east gate and 1601 video door phone lobby camera vieing issue resloved and ok wprking done cable check duct to flat and 2202 intercom cable missing junction side 1901 intercom line ok but phone wall maount and vdp sceen reinstall with cannectoin pending</td></tr><tr><td>15-07-2023 10:29:11</td><td>Kalpesh SubhashGurav</td><td>Old Faulty 4 TB HDD agents new replacement 4 TB HDD Installed Done.</td></tr></tbody></table>					Date Time	Technician Name	Remark	31-07-2023 12:33:52	Ravi Rajbhar	two camera no video work pending back side gate or east gate and 1601 video door phone lobby camera vieing issue resloved and ok wprking done cable check duct to flat and 2202 intercom cable missing junction side 1901 intercom line ok but phone wall maount and vdp sceen reinstall with cannectoin pending	15-07-2023 10:29:11	Kalpesh SubhashGurav	Old Faulty 4 TB HDD agents new replacement 4 TB HDD Installed Done.	
Date Time	Technician Name	Remark													
31-07-2023 12:33:52	Ravi Rajbhar	two camera no video work pending back side gate or east gate and 1601 video door phone lobby camera vieing issue resloved and ok wprking done cable check duct to flat and 2202 intercom cable missing junction side 1901 intercom line ok but phone wall maount and vdp sceen reinstall with cannectoin pending													
15-07-2023 10:29:11	Kalpesh SubhashGurav	Old Faulty 4 TB HDD agents new replacement 4 TB HDD Installed Done.													