Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE9025 **Priority** : Low **Created By :** Admin - Apurva Vajaria Complaint 9773740406 Mob. No. : **Technician Mobile** Technician Ravi Rajbhar 8080922965 Name : Complain Date & Time : 31-07-2023 12:33:52 **Ticket Type : Vendor Details :** Customer's Mobile Company Sai Akashdeep 9773740406 Name : Swapnil Sir Name/Client Chs Ltd Name : Address : Mumbai,,,400064, Maharashtra **AMC Details :** 30-11-2020 12:00:00 Non-Comprehensive Expiry Date : Type : **Product Name :** CCTV "1)2 CCTV Camera is not working. No display at all on the monitor. 2)Flat No. 1901 and 2202 has **Complain** : intercom issue. And Flat No. 1601 has VDP issue. " 802 new door phone sceen install and ok working done and old sceen return to client **Technician Comment :** Desktop - Apurva Vajaria Complain **Operator** : 802 new door phone sceen install and ok working done and old sceen return to client **Remark** :

Status History :		Technician			
5	Date Time	Name	Status	Remark	Sign
	05-08-2023 05:48:29	Ravi Rajbhar	Completed	802 new door phone sceen install and ok working done and old sceen return to client	1. A.
	05-08-2023 05:09:12	Ravi Rajbhar	New		-
	02-08-2023 01:36:00	Ravi Rajbhar	New		-
	31-07-2023 06:35:53	Ravi Rajbhar	Work Pending	two camera no video work pending back side gate or east gate and 1601 video door phone lobby camera vieing issue resloved and ok wprking done cable check duct to flat and 2202 intercom cable missing juction side 1901 intercom line ok but phone wall maount and vdp sceen reinstall with cannectoin pending	
	31-07-2023 12:34:09	Ravi Rajbhar	New		-
Previous	Date Three Technician Manuel				
Complain History :	Date Time	Technician Name		Remark	
	02-09-2023 01:01:27	Shiva Meena	29.08.2023 - Shiva and prashant visited site and PPM done		
	11-08-2023 07:09:26	Ravi Rajbhar	Visited on 02.08.2023 -1)2 camera check but one camera faulty because in side there is water in the camera that damaged the camera and cable check cable ok ohm or power 2)second camera check then reconnection and ok working 3)and one camera main gate west side camera in side water 4)802 - VDP screen remove and taken to office		