

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE9631																																			
Priority :	Low																																		
Created By :	Admin - Apurva Vajaria																																		
Complaint Mob. No. :	9773740406																																		
Technician Name :	Sonu Kumar		Technician Mobile :	8454016444																															
Ticket Type :	Complain	Date & Time :	25-09-2023 06:33:12																																
Vendor Details :																																			
Company Name/Client Name :	Sai Akashdeep Chs Ltd	Customer's Mobile :	9773740406	Name :	Swapnil Sir																														
Address :																																			
Mumbai , , , 400064 , Maharashtra																																			
AMC Details :																																			
Expiry Date :	30-11-2020 12:00:00		Type :	Non-Comprehensive																															
Product Name :	CCTV																																		
Complain :	office DVR beep sound issue																																		
Technician Comment :	Dvr beep saund dvr adufter faulty and new power supply install all working ok																																		
Complain Operator :	Desktop - Apurva Vajaria																																		
Remark :	Dvr beep saund dvr adufter faulty and new power supply install all working ok																																		
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>28-09-2023 03:37:39</td><td>Sonu Kumar</td><td>Completed</td><td>Dvr beep saund dvr adufter faulty and new power supply install all working ok</td><td></td></tr><tr><td>28-09-2023 10:36:50</td><td>Sonu Kumar</td><td>New</td><td></td><td>-</td></tr><tr><td>28-09-2023 10:36:35</td><td>Sonu Kumar</td><td>New</td><td></td><td>-</td></tr><tr><td>26-09-2023 03:25:55</td><td>Sonu Kumar</td><td>Work Pending</td><td>Dvr adufter faulty need to change</td><td></td></tr><tr><td>26-09-2023 11:09:17</td><td>Sonu Kumar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	28-09-2023 03:37:39	Sonu Kumar	Completed	Dvr beep saund dvr adufter faulty and new power supply install all working ok		28-09-2023 10:36:50	Sonu Kumar	New		-	28-09-2023 10:36:35	Sonu Kumar	New		-	26-09-2023 03:25:55	Sonu Kumar	Work Pending	Dvr adufter faulty need to change		26-09-2023 11:09:17	Sonu Kumar	New		-
Date Time	Technician Name	Status	Remark	Sign																															
28-09-2023 03:37:39	Sonu Kumar	Completed	Dvr beep saund dvr adufter faulty and new power supply install all working ok																																
28-09-2023 10:36:50	Sonu Kumar	New		-																															
28-09-2023 10:36:35	Sonu Kumar	New		-																															
26-09-2023 03:25:55	Sonu Kumar	Work Pending	Dvr adufter faulty need to change																																
26-09-2023 11:09:17	Sonu Kumar	New		-																															
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>28-09-2023 12:25:59</td><td>Sonu Kumar</td><td>Cctv camera and intercom and vdp ppm done</td></tr><tr><td>20-09-2023 11:14:38</td><td>Ravi Rajbhar</td><td>1201 intercom issue resloved and ok working done repunching jucation box side bcz cable issue</td></tr></tbody></table>					Date Time	Technician Name	Remark	28-09-2023 12:25:59	Sonu Kumar	Cctv camera and intercom and vdp ppm done	20-09-2023 11:14:38	Ravi Rajbhar	1201 intercom issue resloved and ok working done repunching jucation box side bcz cable issue																					
Date Time	Technician Name	Remark																																	
28-09-2023 12:25:59	Sonu Kumar	Cctv camera and intercom and vdp ppm done																																	
20-09-2023 11:14:38	Ravi Rajbhar	1201 intercom issue resloved and ok working done repunching jucation box side bcz cable issue																																	