## Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$ 

Service Status Det	ails : VE11271					
Priority:	Low					
Created By:	Admin - Apurva Vajaria					
Complaint Mob. No. :	9922942248					
Technician Name:	Siddhesh Chavan		Technician	Technician Mobile : 80809229		
Ticket Type :	Complain	Date & Time :	01-04-2024 11:09:46			
Vendor Details :						
Company Name/Client Name :	Brookhil Chs	Customer's Mobile	9922942248		Name :	Swati Mam
Address :						
Mumbai , , , , Mah	arashtra					
AMC Details :						
Expiry Date :	01-01-1970 05:30:0	00	Type:			
<b>Product Name:</b>	Access					
Complain:	Lobby backside biometric off issue flat no. 605 intercom off issue flat no. 205 in biometric finger and face not accepting					
Technician Comment :	lobby Biometric take to office for checking and one camera issue received 605 Intercom issue resolved 205 person not avelable 905 2601 finger adding done					
Complain Operator :	Desktop - Apurva Vajaria					
Remark:	lobby Biometric take to office for checking and one camera issue received 605 Intercom issue resolved 205 person not avelable 905 2601 finger adding done					
<b>Status History:</b>	Date Time	Technician Name	Status	1	Remark	Sign
	03-04-2024 05:03:43	Siddhesh Chavan	Work Pending	lobby Biometric take to office for checking and one camera issue received 605 Intercom issue resolved 205 person not avelable 905 2601 finger adding done		\$
	03-04-2024 11:08:16	_	New			-
	01-04-2024 06:27:25	Siddhesh Chavan	New			-
Previous Complain History	Date Time	Technician Name	Remark			
	26-06-2024 03:37:32					
	25-06-2024 10:28:11	Atique Salmani	Power consumption so lift camera become off and now it's working ok and 2401 intercom issue resolved by from duct side cable issue so swap cable and working ok and basement exit switch issue sonthere is asmall swich in sapare so use that switch working ok but need big size swich in next visit all cctv working ok.			