




# Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
Support : | W : www.vallabhenterprises.com  
E : vallabhsecure@yahoo.co.in

<b>Service Status Details : VE8355</b>																									
<b>Priority :</b>	Low																								
<b>Created By :</b>	Admin - Apurva Vajaria																								
<b>Complaint Mob. No. :</b>	9922942248																								
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984																					
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	16-05-2023 10:05:50																						
<b>Vendor Details :</b>																									
Company Name/Client Name :	Brookhil Chs	Customer's Mobile :	9922942248	Name :	Swati Mam																				
<b>Address :</b>																									
Mumbai , , , , Maharashtra																									
<b>AMC Details :</b>																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
<b>Product Name :</b>	CCTV																								
<b>Complain :</b>	3 camera not working and some recording need to show to swati madam																								
<b>Technician Comment :</b>	D6 and D 16 lobby camera parking area issue resolved working ok and terrace camera Poe selector/injector need to changed.crimping done																								
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																								
<b>Remark :</b>	D6 and D 16 lobby camera parking area issue resolved working ok and terrace camera Poe selector/injector need to changed.crimping done																								
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>17-05-2023 04:25:22</td><td>Atique Salmani</td><td>Work Pending</td><td>D6 and D 16 lobby camera parking area issue resolved working ok and terrace camera Poe selector/injector need to changed.crimping done</td><td></td></tr><tr><td>17-05-2023 10:31:52</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr><tr><td>16-05-2023 10:06:14</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	17-05-2023 04:25:22	Atique Salmani	Work Pending	D6 and D 16 lobby camera parking area issue resolved working ok and terrace camera Poe selector/injector need to changed.crimping done		17-05-2023 10:31:52	Atique Salmani	New		-	16-05-2023 10:06:14	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																					
17-05-2023 04:25:22	Atique Salmani	Work Pending	D6 and D 16 lobby camera parking area issue resolved working ok and terrace camera Poe selector/injector need to changed.crimping done																						
17-05-2023 10:31:52	Atique Salmani	New		-																					
16-05-2023 10:06:14	Atique Salmani	New		-																					
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>10-08-2023 04:53:19</td><td>Kalpesh SubhashGurav</td><td>Extracted system extension number details 14 th Floor Camera Fitting Done Lobby Security Ext.400 Display Problem Solved.</td></tr><tr><td>07-08-2023 12:44:42</td><td>Kalpesh SubhashGurav</td><td>2701- Intercom Line disturbance issue 205- Intercom line Not Required 2603- Flat Lock 1603- He will call when he brings the telephone 1401- Intercom line Not Required 1905- Intercom line Not Required 1703- Intercom Line OK Telephone Faulty (Ringer Issue) ☐</td></tr></tbody></table>					Date Time	Technician Name	Remark	10-08-2023 04:53:19	Kalpesh SubhashGurav	Extracted system extension number details 14 th Floor Camera Fitting Done Lobby Security Ext.400 Display Problem Solved.	07-08-2023 12:44:42	Kalpesh SubhashGurav	2701- Intercom Line disturbance issue 205- Intercom line Not Required 2603- Flat Lock 1603- He will call when he brings the telephone 1401- Intercom line Not Required 1905- Intercom line Not Required 1703- Intercom Line OK Telephone Faulty (Ringer Issue) ☐											
Date Time	Technician Name	Remark																							
10-08-2023 04:53:19	Kalpesh SubhashGurav	Extracted system extension number details 14 th Floor Camera Fitting Done Lobby Security Ext.400 Display Problem Solved.																							
07-08-2023 12:44:42	Kalpesh SubhashGurav	2701- Intercom Line disturbance issue 205- Intercom line Not Required 2603- Flat Lock 1603- He will call when he brings the telephone 1401- Intercom line Not Required 1905- Intercom line Not Required 1703- Intercom Line OK Telephone Faulty (Ringer Issue) ☐																							