

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE8959															
Priority :	Low														
Created By :	Admin - Apurva Vajaria														
Complaint Mob. No. :	9922942248														
Technician Name :	Pravin Jagade		Technician Mobile :	7262044153											
Ticket Type :	Complain	Date & Time :	25-07-2023 10:19:32												
Vendor Details :															
Company Name/Client Name :	Brookhil Chs	Customer's Mobile :	9922942248	Name :	Swati Mam										
Address :															
Mumbai , , , Maharashtra															
AMC Details :															
Expiry Date :	01-01-1970 05:30:00		Type :												
Product Name :	CCTV														
Complain :	5th floor and 20th floor camera on off issue														
Technician Comment :															
Complain Operator :	Desktop - Apurva Vajaria														
Remark :															
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>25-07-2023 10:19:46</td><td>PravinJagade</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	25-07-2023 10:19:46	PravinJagade	New		-
Date Time	Technician Name	Status	Remark	Sign											
25-07-2023 10:19:46	PravinJagade	New		-											
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>10-08-2023 04:53:19</td><td>Kalpesh SubhashGurav</td><td>Extracted system extension number details 14 th Floor Camera Fitting Done Lobby Security Ext.400 Display Problem Solved.</td></tr><tr><td>07-08-2023 12:44:42</td><td>Kalpesh SubhashGurav</td><td>2701- Intercom Line disturbance issue 205- Intercom line Not Required 2603- Flat Lock 1603- He will call when he brings the telephone 1401- Intercom line Not Required 1905- Intercom line Not Required 1703- Intercom Line OK Telephone Faulty (Ringer Issue) ☐</td></tr></tbody></table>					Date Time	Technician Name	Remark	10-08-2023 04:53:19	Kalpesh SubhashGurav	Extracted system extension number details 14 th Floor Camera Fitting Done Lobby Security Ext.400 Display Problem Solved.	07-08-2023 12:44:42	Kalpesh SubhashGurav	2701- Intercom Line disturbance issue 205- Intercom line Not Required 2603- Flat Lock 1603- He will call when he brings the telephone 1401- Intercom line Not Required 1905- Intercom line Not Required 1703- Intercom Line OK Telephone Faulty (Ringer Issue) ☐	
Date Time	Technician Name	Remark													
10-08-2023 04:53:19	Kalpesh SubhashGurav	Extracted system extension number details 14 th Floor Camera Fitting Done Lobby Security Ext.400 Display Problem Solved.													
07-08-2023 12:44:42	Kalpesh SubhashGurav	2701- Intercom Line disturbance issue 205- Intercom line Not Required 2603- Flat Lock 1603- He will call when he brings the telephone 1401- Intercom line Not Required 1905- Intercom line Not Required 1703- Intercom Line OK Telephone Faulty (Ringer Issue) ☐													