







Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE2000																																			
Priority :	Low																																		
Created By :	Admin - Apurva Vajaria																																		
Complaint Mob. No. :	9820702766																																		
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																															
Ticket Type :	Complain	Date & Time :	12-10-2020 10:16:40																																
Vendor Details :																																			
Company Name/Client Name :	Pearly Shell Apts CHSL	Customer's Mobile :	9820702766	Name :	Thomos Sir																														
Address :																																			
Mumbai , , , 400064 , Maharashtra																																			
AMC Details :																																			
Expiry Date :	13-03-2021 12:00:00		Type :	Non-Comprehensive																															
Product Name :	Intercom																																		
Complain :	301 intercom issue																																		
Technician Comment :	401 junction box to flat wearing check and new other peair used and ok working phone and 1802 1001 301 ok working only check																																		
Complain Operator :	Desktop - Apurva Vajaria																																		
Remark :	401 junction box to flat wearing check and new other peair used and ok working phone and 1802 1001 301 ok working only check																																		
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>14-10-2020 01:39:05</td><td>Ravi Rajbhar</td><td>Completed</td><td>401 junction box to flat wearing check and new other peair used and ok working phone and 1802 1001 301 ok working only check</td><td></td></tr><tr><td>14-10-2020 11:30:16</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>12-10-2020 11:11:41</td><td>Ravi Rajbhar</td><td>Work Pending</td><td>1801 line issues solve and 301 phone issue and 401 coming tomorrow 401 pending Clint side</td><td></td></tr><tr><td>12-10-2020 10:16:57</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>12-10-2020 10:16:40</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	14-10-2020 01:39:05	Ravi Rajbhar	Completed	401 junction box to flat wearing check and new other peair used and ok working phone and 1802 1001 301 ok working only check		14-10-2020 11:30:16	Ravi Rajbhar	New		-	12-10-2020 11:11:41	Ravi Rajbhar	Work Pending	1801 line issues solve and 301 phone issue and 401 coming tomorrow 401 pending Clint side		12-10-2020 10:16:57	Ravi Rajbhar	New		-	12-10-2020 10:16:40	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																															
14-10-2020 01:39:05	Ravi Rajbhar	Completed	401 junction box to flat wearing check and new other peair used and ok working phone and 1802 1001 301 ok working only check																																
14-10-2020 11:30:16	Ravi Rajbhar	New		-																															
12-10-2020 11:11:41	Ravi Rajbhar	Work Pending	1801 line issues solve and 301 phone issue and 401 coming tomorrow 401 pending Clint side																																
12-10-2020 10:16:57	Ravi Rajbhar	New		-																															
12-10-2020 10:16:40	Ravi Rajbhar	New		-																															

Previous Complain History :			
	Date Time	Technician Name	Remark
	07-09-2020 01:12:55	Atique Salmani	lift no. 1 instrument changed and installed working ok. ttested by raza
	01-09-2020 12:48:40	Atique Salmani	201 cable issue after check continuity use another pair and working ok and 101 between instrument 2pair cable joint get more much carbon as fungus so rejoin and working ok.