

B K Infotech

Regd. Office : B K InfoTech Basement No 003, Dattani Trade Center Near BMC Office Chandavarkar Road, Borivali West Mumbai - 92
Support : | **W :** <http://www.bkinfotech.in>
E : kalpesh@bkinfotech.in

Service Status Details : BK1157																									
Priority :	High																								
Created By :	Admin - Kalpesh Jain																								
Complaint Mob. No. :	9819829633																								
Technician Name :	Manish Dhangar		Technician Mobile :	9136841712																					
Ticket Type :	Complain	Date & Time :	05-11-2019 03:07:47																						
Vendor Details :																									
Company Name/Client Name :	Tulip	Customer's Mobile :	9819829633	Name :	Tulip Bakulesh Bhai																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	Cctv Amc Service																								
Complain :	amc																								
Technician Comment :	junter install problems not sol in tulips bulging 4 camera line																								
Complain Operator :	Desktop - Kalpesh Jain																								
Remark :	junter install problems not sol in tulips bulging 4 camera line																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>07-11-2019 11:08:55</td><td>Manish Dhangar</td><td>Work Pending</td><td>junter install problems not sol in tulips bulging 4 camera line</td><td></td></tr><tr><td>05-11-2019 03:07:55</td><td>Manish Dhangar</td><td>New</td><td></td><td>-</td></tr><tr><td>05-11-2019 03:07:47</td><td>Manish Dhangar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	07-11-2019 11:08:55	Manish Dhangar	Work Pending	junter install problems not sol in tulips bulging 4 camera line		05-11-2019 03:07:55	Manish Dhangar	New		-	05-11-2019 03:07:47	Manish Dhangar	New		-
Date Time	Technician Name	Status	Remark	Sign																					
07-11-2019 11:08:55	Manish Dhangar	Work Pending	junter install problems not sol in tulips bulging 4 camera line																						
05-11-2019 03:07:55	Manish Dhangar	New		-																					
05-11-2019 03:07:47	Manish Dhangar	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>19-12-2019 11:55:08</td><td>Manish Dhangar</td><td>34 miter 4+1 wire install b.wing lift camera working camera working</td></tr><tr><td>16-12-2019 12:34:55</td><td>GaneshamMudaliar</td><td>all wing Camera set in continues mode</td></tr></tbody></table>					Date Time	Technician Name	Remark	19-12-2019 11:55:08	Manish Dhangar	34 miter 4+1 wire install b.wing lift camera working camera working	16-12-2019 12:34:55	GaneshamMudaliar	all wing Camera set in continues mode											
Date Time	Technician Name	Remark																							
19-12-2019 11:55:08	Manish Dhangar	34 miter 4+1 wire install b.wing lift camera working camera working																							
16-12-2019 12:34:55	GaneshamMudaliar	all wing Camera set in continues mode																							