




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE6016																														
Priority :	Low																													
Created By :	Admin - Apurva Vajaria																													
Complaint Mob. No. :	9702455968																													
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																										
Ticket Type :	Complain	Date & Time :	23-07-2022 10:23:12																											
Vendor Details :																														
Company Name/Client Name :	Rahul Classic A Co Op Hsg Soc. Ltd	Customer's Mobile :	9702455968	Name :	Tushar Sir																									
Address :																														
Mumbai , , , , Maharashtra																														
AMC Details :																														
Expiry Date :	31-03-2021 12:00:00		Type :	Non-Comprehensive																										
Product Name :	Intercom																													
Complain :	Again intercom issue																													
Technician Comment :	intercom issue resolved and ok working done bcs main power supply on / off switch issue and switch remova and direct connection and ok working done																													
Complain Operator :	Desktop - Apurva Vajaria																													
Remark :	intercom issue resolved and ok working done bcs main power supply on / off switch issue and switch remova and direct connection and ok working done																													
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>23-07-2022 04:46:29</td><td>Ravi Rajbhar</td><td>Completed</td><td>intercom issue resolved and ok working done bcs main power supply on / off switch issue and switch remova and direct connection and ok working done</td><td></td></tr><tr><td>23-07-2022 11:18:20</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>23-07-2022 10:23:23</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr><tr><td>23-07-2022 10:23:12</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	23-07-2022 04:46:29	Ravi Rajbhar	Completed	intercom issue resolved and ok working done bcs main power supply on / off switch issue and switch remova and direct connection and ok working done		23-07-2022 11:18:20	Ravi Rajbhar	New		-	23-07-2022 10:23:23	Ravi Rajbhar	New		-	23-07-2022 10:23:12	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																										
23-07-2022 04:46:29	Ravi Rajbhar	Completed	intercom issue resolved and ok working done bcs main power supply on / off switch issue and switch remova and direct connection and ok working done																											
23-07-2022 11:18:20	Ravi Rajbhar	New		-																										
23-07-2022 10:23:23	Ravi Rajbhar	New		-																										
23-07-2022 10:23:12	Ravi Rajbhar	New		-																										
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>20-07-2022 06:45:25</td><td>YogeshDesai</td><td>security guard intercom phone working ok and display also working ok</td></tr><tr><td>11-05-2022 04:46:56</td><td>Siddhesh Chavan</td><td>cctv ppm done and all camera working ok and intrcom system working ok</td></tr></tbody></table>					Date Time	Technician Name	Remark	20-07-2022 06:45:25	YogeshDesai	security guard intercom phone working ok and display also working ok	11-05-2022 04:46:56	Siddhesh Chavan	cctv ppm done and all camera working ok and intrcom system working ok																
Date Time	Technician Name	Remark																												
20-07-2022 06:45:25	YogeshDesai	security guard intercom phone working ok and display also working ok																												
11-05-2022 04:46:56	Siddhesh Chavan	cctv ppm done and all camera working ok and intrcom system working ok																												