




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE12980																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	9820715724																			
Technician Name :	Ravi Rajbhar		Technician Mobile :	8080922965																
Ticket Type :	Complain	Date & Time :	14-10-2024 03:10:47																	
Vendor Details :																				
Company Name/Client Name :	Mittal Court New Office 15th Floor	Customer's Mobile :	9820715724	Name :	Umesh Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	1 camera light continuous on issue and 6th floor office 1 new phone programming need to do																			
Technician Comment :	15 th floor one cmaera change and old camera remove and take to office And urvil sir cabin black phone install with programing done sat date and time with speed dail in set phone																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	15 th floor one cmaera change and old camera remove and take to office And urvil sir cabin black phone install with programing done sat date and time with speed dail in set phone																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>14-10-2024 06:00:38</td><td>Ravi Rajbhar</td><td>Completed</td><td>15 th floor one cmaera change and old camera remove and take to office And urvil sir cabin black phone install with programing done sat date and time with speed dail in set phone</td><td></td></tr><tr><td>14-10-2024 03:11:02</td><td>Ravi Rajbhar</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	14-10-2024 06:00:38	Ravi Rajbhar	Completed	15 th floor one cmaera change and old camera remove and take to office And urvil sir cabin black phone install with programing done sat date and time with speed dail in set phone		14-10-2024 03:11:02	Ravi Rajbhar	New		-
Date Time	Technician Name	Status	Remark	Sign																
14-10-2024 06:00:38	Ravi Rajbhar	Completed	15 th floor one cmaera change and old camera remove and take to office And urvil sir cabin black phone install with programing done sat date and time with speed dail in set phone																	
14-10-2024 03:11:02	Ravi Rajbhar	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>18-10-2024 11:28:01</td><td>PravinJagade</td><td>15 th floor 1 camera install working done.</td></tr><tr><td>09-10-2024 05:22:22</td><td>Ravi Rajbhar</td><td>15 th floor cmaera one cmaera light continues on then restart poe switch and ok working done but under observation going on And 6 floor ppm done off cctv and epbax system all ok working done And urvil sir cabin instrument issue need to change</td></tr></tbody></table>					Date Time	Technician Name	Remark	18-10-2024 11:28:01	PravinJagade	15 th floor 1 camera install working done.	09-10-2024 05:22:22	Ravi Rajbhar	15 th floor cmaera one cmaera light continues on then restart poe switch and ok working done but under observation going on And 6 floor ppm done off cctv and epbax system all ok working done And urvil sir cabin instrument issue need to change						
Date Time	Technician Name	Remark																		
18-10-2024 11:28:01	PravinJagade	15 th floor 1 camera install working done.																		
09-10-2024 05:22:22	Ravi Rajbhar	15 th floor cmaera one cmaera light continues on then restart poe switch and ok working done but under observation going on And 6 floor ppm done off cctv and epbax system all ok working done And urvil sir cabin instrument issue need to change																		