




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE13035																									
Priority :	Low																								
Created By :	Admin - Apurva Vajaria																								
Complaint Mob. No. :	9820715724																								
Technician Name :	Pravin Jagade		Technician Mobile :	7262044153																					
Ticket Type :	Complain	Date & Time :	18-10-2024 11:28:01																						
Vendor Details :																									
Company Name/Client Name :	Mittal Court New Office 15th Floor	Customer's Mobile :	9820715724	Name :	Umesh Sir																				
Address :																									
Mumbai , , , , Maharashtra																									
AMC Details :																									
Expiry Date :	01-01-1970 05:30:00		Type :																						
Product Name :	CCTV																								
Complain :	recently changed 15th floor camera night vision not working																								
Technician Comment :	15 th floor 1 camera install working done.																								
Complain Operator :	Desktop - Apurva Vajaria																								
Remark :	15 th floor 1 camera install working done.																								
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>28-10-2024 02:16:36</td><td>PravinJagade</td><td>Completed</td><td>15 th floor 1 camera install working done.</td><td></td></tr><tr><td>28-10-2024 10:22:44</td><td>PravinJagade</td><td>New</td><td></td><td>-</td></tr><tr><td>19-10-2024 10:57:21</td><td>PravinJagade</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	28-10-2024 02:16:36	PravinJagade	Completed	15 th floor 1 camera install working done.		28-10-2024 10:22:44	PravinJagade	New		-	19-10-2024 10:57:21	PravinJagade	New		-
Date Time	Technician Name	Status	Remark	Sign																					
28-10-2024 02:16:36	PravinJagade	Completed	15 th floor 1 camera install working done.																						
28-10-2024 10:22:44	PravinJagade	New		-																					
19-10-2024 10:57:21	PravinJagade	New		-																					
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>14-10-2024 03:10:47</td><td>Ravi Rajbhar</td><td>15 th floor one cmaera change and old camera remove and take to office And urvil sir cabin black phone install with proگرامing done sat date and time with speed dail in set phone</td></tr><tr><td>09-10-2024 05:22:22</td><td>Ravi Rajbhar</td><td>15 th floor cmaera one cmaera light continues on then restart poe switch and ok working done but under observation going on And 6 floor ppm done off cctv and epbax system all ok working done And urvil sir cabin instrument issue need to change</td></tr></tbody></table>					Date Time	Technician Name	Remark	14-10-2024 03:10:47	Ravi Rajbhar	15 th floor one cmaera change and old camera remove and take to office And urvil sir cabin black phone install with proگرامing done sat date and time with speed dail in set phone	09-10-2024 05:22:22	Ravi Rajbhar	15 th floor cmaera one cmaera light continues on then restart poe switch and ok working done but under observation going on And 6 floor ppm done off cctv and epbax system all ok working done And urvil sir cabin instrument issue need to change											
Date Time	Technician Name	Remark																							
14-10-2024 03:10:47	Ravi Rajbhar	15 th floor one cmaera change and old camera remove and take to office And urvil sir cabin black phone install with proگرامing done sat date and time with speed dail in set phone																							
09-10-2024 05:22:22	Ravi Rajbhar	15 th floor cmaera one cmaera light continues on then restart poe switch and ok working done but under observation going on And 6 floor ppm done off cctv and epbax system all ok working done And urvil sir cabin instrument issue need to change																							