

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE2253																																			
Priority :	High																																		
Created By :	Admin - Apurva Vajaria																																		
Complaint Mob. No. :	9820974083																																		
Technician Name :	Yasin Shaikh		Technician Mobile :	8689802313																															
Ticket Type :	Call Basis	Date & Time :	20-11-2020 04:49:36																																
Vendor Details :																																			
Company Name/Client Name :	Sahajanand Developers	Customer's Mobile :	9820974083	Name :	Vicky - Viranchi - Chirag																														
Address :																																			
Mumbai , , , , Maharashtra																																			
AMC Details :																																			
Expiry Date :	01-01-1970 05:30:00		Type :																																
Product Name :	Intercom																																		
Complain :	intercom issue																																		
Technician Comment :	G wing & H wing new vdp install done total =22																																		
Complain Operator :	Desktop - Apurva Vajaria																																		
Remark :	system dead brought for repairing. EPABX sent back to client as its not repairable																																		
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>11-12-2020 12:37:53</td><td>YasinShaikh</td><td>Completed</td><td></td><td>-</td></tr><tr><td>30-11-2020 11:10:50</td><td>YasinShaikh</td><td>Awaiting Spares</td><td></td><td>-</td></tr><tr><td>26-11-2020 07:00:32</td><td>YasinShaikh</td><td>In Progress</td><td>G wing & H wing new vdp install done total =22</td><td></td></tr><tr><td>20-11-2020 04:50:04</td><td>YasinShaikh</td><td>New</td><td></td><td>-</td></tr><tr><td>20-11-2020 04:49:36</td><td>YasinShaikh</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	11-12-2020 12:37:53	YasinShaikh	Completed		-	30-11-2020 11:10:50	YasinShaikh	Awaiting Spares		-	26-11-2020 07:00:32	YasinShaikh	In Progress	G wing & H wing new vdp install done total =22		20-11-2020 04:50:04	YasinShaikh	New		-	20-11-2020 04:49:36	YasinShaikh	New		-
Date Time	Technician Name	Status	Remark	Sign																															
11-12-2020 12:37:53	YasinShaikh	Completed		-																															
30-11-2020 11:10:50	YasinShaikh	Awaiting Spares		-																															
26-11-2020 07:00:32	YasinShaikh	In Progress	G wing & H wing new vdp install done total =22																																
20-11-2020 04:50:04	YasinShaikh	New		-																															
20-11-2020 04:49:36	YasinShaikh	New		-																															
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>22-03-2022 10:38:31</td><td>Atique Salmani</td><td>all cctv system remooved epbax door access smoke detector fire panel intrusion pannel door sensor .all material kept in sajanand office . all lock also remooved .</td></tr><tr><td>12-01-2022 04:36:43</td><td>Siddhesh Chavan</td><td>Change the IP Setting & Connector change and machine working ok</td></tr></tbody></table>					Date Time	Technician Name	Remark	22-03-2022 10:38:31	Atique Salmani	all cctv system remooved epbax door access smoke detector fire panel intrusion pannel door sensor .all material kept in sajanand office . all lock also remooved .	12-01-2022 04:36:43	Siddhesh Chavan	Change the IP Setting & Connector change and machine working ok																					
Date Time	Technician Name	Remark																																	
22-03-2022 10:38:31	Atique Salmani	all cctv system remooved epbax door access smoke detector fire panel intrusion pannel door sensor .all material kept in sajanand office . all lock also remooved .																																	
12-01-2022 04:36:43	Siddhesh Chavan	Change the IP Setting & Connector change and machine working ok																																	