## Vallabh Enterprises

**Regd. Office** : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE5746 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 7506373834 **No. :** Technician Siddhesh Chavan **Technician Mobile** 8080922985 Name : : Complain 18-06-2022 07:11:07 **Ticket Type : Date & Time : Vendor Details :** 7506373834 Company Yamunotri Co Op Customer's Mobile Name : Vikash Joshi Name/Client Hsg Society Name : Address : mumbai,,,,Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name :** CCTV **Complain**: Dvr recording need to check on or not and training need to give how recording check and export training done and 2 camera no video issue resolved and all Technician **Comment** : camera working ok Complain Desktop - Apurva Vajaria **Operator** : how recording check and export training done and 2 camera no video issue resolved and all **Remark** : camera working ok **Status History : Date Time Technician Name** Status Remark Sign 18-06-2022 09:02:08 Siddhesh Chavan Completed how recording check and export training done and 2 camera no video issue resolved and all camera working ok 18-06-2022 07:11:31 Siddhesh Chavan New 18-06-2022 07:11:07 Siddhesh Chavan New

Previous Complain History :	Date Time	Technician Name	Remark
	14-06-2022 10:36:39	Atique Salmani	1.Camera nmbr 12 check cable continuity cable joint in middle from joint to camera cable ok and from dvr to joint cable faulty so now camera nmbr 12 off becz cable faulty camera ok .use 2 bnc and 1 d.c 2.camera nmbr 6 lift camera didn't installed soniya also showing no vedeo . 3.camera nmbr 1 maine gate also joint in middle it's totally rushed from joint so it's vewing more disturbance so rejoint after find out the joint and working ok but need to changed cabling boath Gate side cameras cable need approximately 120/130 metr for boath cameras cable standard .4+1 4.camera nmbr 14 water insert in camera lense so it's vewing foggy also miss camera screw for angel set camera 30 meter bullet also need to changed .
	17-05-2022 11:09:45	Prashant Nikalje	work pendi Power supply install dvr side and work completed