




# Vallabh Enterprises

**Regd. Office :** 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067  
**Support : | W :** www.vallabhenterprises.com  
**E :** vallabhsecure@yahoo.co.in

<b>Service Status Details : VE6765</b>																				
<b>Priority :</b>	Low																			
<b>Created By :</b>	Admin - Apurva Vajaria																			
<b>Complaint Mob. No. :</b>	7506373834																			
<b>Technician Name :</b>	Atique Salmani		<b>Technician Mobile :</b>	8080922984																
<b>Ticket Type :</b>	Complain	<b>Date &amp; Time :</b>	05-11-2022 10:26:36																	
<b>Vendor Details :</b>																				
<b>Company Name/Client Name :</b>	Yamunotri Co Op Hsg Society	<b>Customer's Mobile :</b>	7506373834	<b>Name :</b>	Vikash Joshi															
<b>Address :</b>																				
mumbai , , , , Maharashtra																				
<b>AMC Details :</b>																				
<b>Expiry Date :</b>	01-01-1970 05:30:00		<b>Type :</b>																	
<b>Product Name :</b>	Ppm																			
<b>Complain :</b>	cctv ppm need to do																			
<b>Technician Comment :</b>	Dvr end dressing done after dressing a wing lobby camera cable break not getting continueti so need to changed cable also a wing camera + cable need to changed bullet 30 mter cable for boath camera approx 100 meter .																			
<b>Complain Operator :</b>	Desktop - Apurva Vajaria																			
<b>Remark :</b>	Dvr end dressing done after dressing a wing lobby camera cable break not getting continueti so need to changed cable also a wing camera + cable need to changed bullet 30 mter cable for boath camera approx 100 meter .																			
<b>Status History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>05-11-2022 05:47:55</td><td>Atique Salmani</td><td>Completed</td><td>Dvr end dressing done after dressing a wing lobby camera cable break not getting continueti so need to changed cable also a wing camera + cable need to changed bullet 30 mter cable for boath camera approx 100 meter .</td><td></td></tr><tr><td>05-11-2022 10:26:41</td><td>Atique Salmani</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	05-11-2022 05:47:55	Atique Salmani	Completed	Dvr end dressing done after dressing a wing lobby camera cable break not getting continueti so need to changed cable also a wing camera + cable need to changed bullet 30 mter cable for boath camera approx 100 meter .		05-11-2022 10:26:41	Atique Salmani	New		-
Date Time	Technician Name	Status	Remark	Sign																
05-11-2022 05:47:55	Atique Salmani	Completed	Dvr end dressing done after dressing a wing lobby camera cable break not getting continueti so need to changed cable also a wing camera + cable need to changed bullet 30 mter cable for boath camera approx 100 meter .																	
05-11-2022 10:26:41	Atique Salmani	New		-																
<b>Previous Complain History :</b>	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>04-11-2022 04:00:00</td><td>Atique Salmani</td><td>B wing lift camera issue resolved by use baloon boath end and it's working ok</td></tr><tr><td>03-11-2022 10:44:34</td><td>PravinJagade</td><td>lift camera working done.</td></tr></tbody></table>					Date Time	Technician Name	Remark	04-11-2022 04:00:00	Atique Salmani	B wing lift camera issue resolved by use baloon boath end and it's working ok	03-11-2022 10:44:34	PravinJagade	lift camera working done.						
Date Time	Technician Name	Remark																		
04-11-2022 04:00:00	Atique Salmani	B wing lift camera issue resolved by use baloon boath end and it's working ok																		
03-11-2022 10:44:34	PravinJagade	lift camera working done.																		