




Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE6984																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	7506373834																			
Technician Name :	Siddhesh Chavan		Technician Mobile :	8080922985																
Ticket Type :	Complain	Date & Time :	01-12-2022 10:53:50																	
Vendor Details :																				
Company Name/Client Name :	Yamunotri Co Op Hsg Society	Customer's Mobile :	7506373834	Name :	Vikash Joshi															
Address :																				
mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	need to check camera and make the report of faulty																			
Technician Comment :	1) B wing lift camera faulty cable ok 2) a wing out side passage camera stan break camera ok cable faulty and 3) a wing lobby camera ok cable issue need to change 4) b wing terrace cable issue and camera not found																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	1) B wing lift camera faulty cable ok 2) a wing out side passage camera stan break camera ok cable faulty and 3) a wing lobby camera ok cable issue need to change 4) b wing terrace cable issue and camera not found																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>01-12-2022 12:23:53</td><td>Siddhesh Chavan</td><td>Completed</td><td>1) B wing lift camera faulty cable ok 2) a wing out side passage camera stan break camera ok cable faulty and 3) a wing lobby camera ok cable issue need to change 4) b wing terrace cable issue and camera not found</td><td></td></tr><tr><td>01-12-2022 10:53:58</td><td>Siddhesh Chavan</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	01-12-2022 12:23:53	Siddhesh Chavan	Completed	1) B wing lift camera faulty cable ok 2) a wing out side passage camera stan break camera ok cable faulty and 3) a wing lobby camera ok cable issue need to change 4) b wing terrace cable issue and camera not found		01-12-2022 10:53:58	Siddhesh Chavan	New		-
Date Time	Technician Name	Status	Remark	Sign																
01-12-2022 12:23:53	Siddhesh Chavan	Completed	1) B wing lift camera faulty cable ok 2) a wing out side passage camera stan break camera ok cable faulty and 3) a wing lobby camera ok cable issue need to change 4) b wing terrace cable issue and camera not found																	
01-12-2022 10:53:58	Siddhesh Chavan	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>05-11-2022 10:26:36</td><td>Atique Salmani</td><td>Dvr end dressing done after dressing a wing lobby camera cable break not getting continueti so need to changed cable also a wing camera + cable need to changed bullet 30 mter cable for boath camera approx 100 meter .</td></tr><tr><td>04-11-2022 04:00:00</td><td>Atique Salmani</td><td>B wing lift camera issue resolved by use baloon boath end and it's working ok</td></tr></tbody></table>					Date Time	Technician Name	Remark	05-11-2022 10:26:36	Atique Salmani	Dvr end dressing done after dressing a wing lobby camera cable break not getting continueti so need to changed cable also a wing camera + cable need to changed bullet 30 mter cable for boath camera approx 100 meter .	04-11-2022 04:00:00	Atique Salmani	B wing lift camera issue resolved by use baloon boath end and it's working ok						
Date Time	Technician Name	Remark																		
05-11-2022 10:26:36	Atique Salmani	Dvr end dressing done after dressing a wing lobby camera cable break not getting continueti so need to changed cable also a wing camera + cable need to changed bullet 30 mter cable for boath camera approx 100 meter .																		
04-11-2022 04:00:00	Atique Salmani	B wing lift camera issue resolved by use baloon boath end and it's working ok																		