Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\$

Service Status	Details: VE11522									
Priority:	Low									
Created By:	Admin - Apurva Vajaria									
Complaint Mob. No. :	7352454804									
Technician Name :	Pravin Jagade		Technician Mobile :	7262044153						
Ticket Type :	Complain Date & Time :		29-04-2024 05:21:32	024 05:21:32						
Vendor Details :										
Company Name/Client Name :	Rahul International - Mira Road	Customer's Mobile :	7352454804	Name :	Vikash Sir					
Address:										
Mumbai , , , ,	Maharashtra									
AMC Details :										
Expiry Date :	01-01-1970 05:30:00		Type:							
Product Name :	CCTV									
Complain:	113 out side Class 306 Class 403 Class 503 Class 504 Get no 3 right and left side Football ground AI IPC camera 806 out side 2 and 1 All cameras offline									
Technician Comment :	806 camera falty Studio no 5 camera falty 504 camera reinstall because camera falty 302 and 303 camera reinstall working done Ground floor dvr offine issue resolve working done Total 5 camera take for repering parpose to office.									
Complain Operator :	Desktop - Apurva Vajaria									
Remark:	806 camera falty Studio no 5 camera falty 504 camera reinstall because camera falty 302 and 303 camera reinstall working done Ground floor dvr offine issue resolve working done Total 5 camera take for repering parpose to office.									

Status History :	Date Time		echnician Name		tus	Remark	Sign
	06-06-2024 03:20:04	PravinJ	PravinJagade		ing	806 camera falty Studio no 5 camera falty 504 camera reinstall because camera falty 302 and 303 camera reinstall working done Ground floor dvr offine issue resolve working done Total 5 camera take for repering parpose to office.	Sovo
	03-06-2024 12:42:36	PravinJ	PravinJagade				-
	23-05-2024 02:50:31	PravinJagade		Client Side		806 out side bullet camera installation done working ok 806 out side dome camera installation done working ok Room no 403 camera not install because camera side location selling pack.	AISMILL
	23-05-2024 11:20:32	PravinJ	PravinJagade				-
	21-05-2024 11:06:20	PravinJ	PravinJagade				-
	16-05-2024 10:55:22	PravinJagade		New			-
	02-05-2024 04:01:11	PravinJ	PravinJagade		t ing	1. 113 out side camera blinking issue resolved working ok and class no 306 camera blinking issue resolved working ok 2. gate no 3 right and left side camera off issue resolved working ok and football and ground area and all IPC camera off issue resolved working ok 3. 403 camera collect ip 108 4. 8th floor .806 out side 2 camera collect for reparing purpose camera ip .192.168.2.72/192.168.2.38 5. 1 camera cleaning done and 5th floor 1 camera angle setting done 6. and 503.504camera ceking pending	D
	30-04-2024 10:13:02	PravinJ	PravinJagade				-
Previous Complain	Date Time Technician N		ame	ne Remark			
History :	03-07-2024 10:50:17 Sonu Kuma		onu Kumar		1. Ground floor lobby2 1 camera off issue resolved working ok 2. Counselor office 1 camera off issue resolved working ok 3. 5th floor 8 camera off issue resolved working ok 4. Ground floor 2 camera angle setting done 5. 1st floor passage 2 camera angle setting done		

1 switch off issue resolved working ok

28-06-2024 12:41:44

Sonu Kumar