## Vallabh Enterprises

**Regd. Office** : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE12539 **Priority** : Low **Created By :** Admin - Apurva Vajaria Complaint 7352454804 Mob. No. : Technician Atique Salmani **Technician Mobile** 8080922984 Name : Complain Date & Time : 26-08-2024 12:05:04 **Ticket Type : Vendor Details :** Customer's Mobile Rahul International -7352454804 Vikash Sir Company Name : Name/Client Mira Road Name : Address : Mumbai,,,, Maharashtra **AMC Details :** 01-01-1970 05:30:00 Expiry Date : Type : **Product Name** CCTV **Complain** : Admin 2 107 out side 410 out side Bullet camera installing panding Ai IPC football ground 5th floor Corridor side 806 out side All cameras are offline. Technician Admin 2 vedeo baloon changed issue resolved working ok 502 out side new camera installation **Comment**: done working ok. 410 out side camera installation done set angel working ok staircase 8th floor done camera was off last 3 months dome camera issue so cahnged working ok also ip was deleted by some one so assign new ip 2.250and working ok. Complain Desktop - Apurva Vajaria **Operator** : **Remark** : Admin 2 vedeo baloon changed issue resolved working ok 502 out side new camera installation done working ok. 410 out side camera installation done set angel working ok staircase 8th floor done camera was off last 3 months dome camera issue so cahnged working ok also ip was deleted by some one so assign new ip 2.250and working ok.

Status History		_	-			
:	Date Time	Technician Name	Status		Remark	Sign
	28-08-2024 05:14:21	Atique Salmani	Completed		Admin 2 vedeo baloon changed issue resolved working ok 502 out side new camera installation done working ok. 410 out side camera installation done set angel working ok staircase 8th floor done camera was off last 3 months dome camera issue so cahnged working ok also ip was deleted by some one so assign new ip 2.250and working ok.	V
	28-08-2024 05:14:21	Atique Salmani	Completed		Admin 2 vedeo baloon changed issue resolved working ok 502 out side new camera installation done working ok. 410 out side camera installation done set angel working ok staircase 8th floor done camera was off last 3 months dome camera issue so cahnged working ok also ip was deleted by some one so assign new ip 2.250and working ok.	Ver
	28-08-2024 05:14:21	Atique Salmani	Completed		Admin 2 vedeo baloon changed issue resolved working ok 502 out side new camera installation done working ok. 410 out side camera installation done set angel working ok staircase 8th floor done camera was off last 3 months dome camera issue so cahnged working ok also ip was deleted by some one so assign new ip 2.250and working ok.	V
	28-08-2024 05:14:20	Atique Salmani	Completed		Admin 2 vedeo baloon changed issue resolved working ok 502 out side new camera installation done working ok. 410 out side camera installation done set angel working ok staircase 8th floor done camera was off last 3 months dome camera issue so cahnged working ok also ip was deleted by some one so assign new ip 2.250and working ok.	×
	28-08-2024 01:09:52	Atique Salmani	New			-
	28-08-2024 10:46:57	Atique Salmani	New			-
	26-08-2024 12:05:11	Atique Salmani	New			-
Previous Complain History :	Date Time Technician		Name	Name Remark		
	28-08-2024 03:23:49 Atique Sala		mani	ani In Rahul sir cabin view painding because some material reqired so Its painding .		rial reqired
	17-08-2024 12:58:	17-08-2024 12:58:20 Sonu Kuma				