Vallabh Enterprises

 $\label{eq:Regd.office:401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067 \\ \text{Support:} \mid \textbf{W}: www.vallabhenterprises.com \\ \textbf{E}: vallabhsecure@yahoo.co.in \\ \end{cases}$

Service Status De							
Priority:	Low						
Created By:	Admin - Apurva Vajaria						
Complaint Mob. No. :	7352454804						
Technician Name :	Rahul Mhapralkar		Techni :	cian Mobile	9168762949		
Ticket Type:	Complain	Date & Time :	11-08-2	2025 03:23:57			
Vendor Details :	Vendor Details :						
Company Name/Client Name :	Rahul International - Mira Road	Customer's Mobi	ile 735245	54804	Name :	Vikash Sir	
Address:							
Mumbai , , , , Ma	harashtra						
AMC Details :							
Expiry Date :	01-01-1970 05:30:00		Type:				
Product Name:	CCTV						
Complain:	1)Class room 801 after check need to install 2)513 Out side 2 offline 3)Football ground -Offline 4)AI IPC (Without name) 5)Gate no 5 left side -Offline						
Technician Comment :	505 out side camera issue resolved now working normally, nd 513 out side camera issue taken for repair. 802 and 805 b camera channel change now working normally.						
Complain Operator :	Desktop - Apurva Vajaria						
Remark:	505 out side camera issue resolved now working normally, nd 513 out side camera issue taken for repair. 802 and 805 b camera channel change now working normally.						
Status History:	Date Time	Technician Name	Status	Re	emark	Sign	
	13-08-2025 04:02:21	Rahul Mhapralkar	Completed	nd 513 out side	vorking normally, e camera issue r. 802 and 805 b el change now	VA-	
	13-08-2025 04:02:20	Rahul Mhapralkar	Completed	nd 513 out side	vorking normally, e camera issue r. 802 and 805 b el change now	Aug	
	13-08-2025 12:29:09	Rahul Mhapralkar	New			-	
	11-08-2025	Rahul Mhapralkar	New				

Previous
Complain
History :

Date Time	Technician Name	Remark
14-11-2025 10:43:58	MaroofRaza	401 outside replace camera install working
26-09-2025 11:16:24	MaroofRaza	1 football ground camera working. counselor room camera working admin camera working 401 passage camera faulty power issue bullet camera collect. principle cabin camera reset pending because principle sir working continue.