

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE15804					
Priority :	Low				
Created By :	Admin - Apurva Vajaria				
Complaint Mob. No. :	7352454804				
Technician Name :	Prashant Paswan		Technician Mobile :	6202751495	
Ticket Type :	Complain	Date & Time :	16-09-2025 12:15:31		
Vendor Details :					
Company Name/Client Name :	Rahul International - Mira Road	Customer's Mobile :	7352454804	Name :	Vikash Sir
Address :					
Mumbai , , , , Maharashtra					
AMC Details :					
Expiry Date :	01-01-1970 05:30:00		Type :		
Product Name :	CCTV				
Complain :	513 out side 2 offline Main entry offline 7th flr offline Material room out side offline 302 Angle set				
Technician Comment :	513 out side camera pending,707 camera faulty,8th floor material out side camera faulty collect,laberray out side camera				
Complain Operator :	Desktop - Apurva Vajaria				
Remark :	513 out side camera pending,707 camera faulty,8th floor material out side camera faulty collect,laberray out side camera 22.09.2025 - Rahul visited - football room camera issue not working/513 room camera installed/707 camera installed/Material room camera not adding to NVR/401 camera cable faulty orange pair/Principle room analog camera issue				
Status History :	Date Time	Technician Name	Status	Remark	Sign
	23-09-2025 05:12:24	Prashant Paswan	New		-
	23-09-2025 03:45:43	Prashant Paswan	New		-
	22-09-2025 05:04:58	Prashant Paswan	New		-
	22-09-2025 05:04:46	Prashant Paswan	Work Pending		-
	16-09-2025 04:32:00	Prashant Paswan	Completed	513 out side camera pending,707 camera faulty,8th floor material out side camera faulty collect,laberray out side camera	
	16-09-2025 12:15:46	Prashant Paswan	New		-

Previous Complain History :			
	Date Time	Technician Name	Remark
	14-11-2025 10:43:58	MaroofRaza	401 outside replace camera install working
	26-09-2025 11:16:24	MaroofRaza	1 football ground camera working. counselor room camera working admin camera working 401 passage camera faulty power issue bullet camera collect. principle cabin camera reset pending because principle sir working continue.