

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE15886																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	7352454804																			
Technician Name :	Maroof Raza		Technician Mobile :	7761863562																
Ticket Type :	Complain	Date & Time :	26-09-2025 11:16:24																	
Vendor Details :																				
Company Name/Client Name :	Rahul International - Mira Road	Customer's Mobile :	7352454804	Name :	Vikash Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	Principle mobile online need to do																			
Technician Comment :																				
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	1 football ground camera working. counselor room camera working admin camera working 401 passage camera faulty power issue bullet camera collect. principle cabin camera reset pending because principle sir working continue.																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>09-10-2025 03:19:42</td><td>MaroofRaza</td><td>Completed</td><td></td><td>-</td></tr><tr><td>26-09-2025 11:17:23</td><td>MaroofRaza</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	09-10-2025 03:19:42	MaroofRaza	Completed		-	26-09-2025 11:17:23	MaroofRaza	New		-
Date Time	Technician Name	Status	Remark	Sign																
09-10-2025 03:19:42	MaroofRaza	Completed		-																
26-09-2025 11:17:23	MaroofRaza	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>14-11-2025 10:43:58</td><td>MaroofRaza</td><td>401 outside replace camera install working</td></tr><tr><td>16-09-2025 12:15:31</td><td>Prashant Paswan</td><td>513 out side camera pending,707 camera faulty,8th floor material out side camera faulty collect,laberray out side camera 22.09.2025 - Rahul visited - football room camera issue not working/513 room camera installed/707 camera installed/Material room camera not adding to NVR/401 camera cable faulty orange pair/Principle room analog camera issue</td></tr></tbody></table>					Date Time	Technician Name	Remark	14-11-2025 10:43:58	MaroofRaza	401 outside replace camera install working	16-09-2025 12:15:31	Prashant Paswan	513 out side camera pending,707 camera faulty,8th floor material out side camera faulty collect,laberray out side camera 22.09.2025 - Rahul visited - football room camera issue not working/513 room camera installed/707 camera installed/Material room camera not adding to NVR/401 camera cable faulty orange pair/Principle room analog camera issue						
Date Time	Technician Name	Remark																		
14-11-2025 10:43:58	MaroofRaza	401 outside replace camera install working																		
16-09-2025 12:15:31	Prashant Paswan	513 out side camera pending,707 camera faulty,8th floor material out side camera faulty collect,laberray out side camera 22.09.2025 - Rahul visited - football room camera issue not working/513 room camera installed/707 camera installed/Material room camera not adding to NVR/401 camera cable faulty orange pair/Principle room analog camera issue																		