

Vallabh Enterprises

Regd. Office : 401,shanti kutir,shivaji road,near thakur international school,kandivali(west) mumbai - 400067
Support : | W : www.vallabhenterprises.com
E : vallabhsecure@yahoo.co.in

Service Status Details : VE16245																				
Priority :	Low																			
Created By :	Admin - Apurva Vajaria																			
Complaint Mob. No. :	7352454804																			
Technician Name :	Maroof Raza		Technician Mobile :	7761863562																
Ticket Type :	Complain	Date & Time :	14-11-2025 10:43:58																	
Vendor Details :																				
Company Name/Client Name :	Rahul International - Mira Road	Customer's Mobile :	7352454804	Name :	Vikash Sir															
Address :																				
Mumbai , , , , Maharashtra																				
AMC Details :																				
Expiry Date :	01-01-1970 05:30:00		Type :																	
Product Name :	CCTV																			
Complain :	401 passage replacement camera need to install																			
Technician Comment :	401 outside replace camera install working																			
Complain Operator :	Desktop - Apurva Vajaria																			
Remark :	401 outside replace camera install working																			
Status History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Status</th><th>Remark</th><th>Sign</th></tr></thead><tbody><tr><td>14-11-2025 04:00:19</td><td>MaroofRaza</td><td>Completed</td><td>401 outside replace camera install working</td><td></td></tr><tr><td>14-11-2025 10:44:13</td><td>MaroofRaza</td><td>New</td><td></td><td>-</td></tr></tbody></table>					Date Time	Technician Name	Status	Remark	Sign	14-11-2025 04:00:19	MaroofRaza	Completed	401 outside replace camera install working		14-11-2025 10:44:13	MaroofRaza	New		-
Date Time	Technician Name	Status	Remark	Sign																
14-11-2025 04:00:19	MaroofRaza	Completed	401 outside replace camera install working																	
14-11-2025 10:44:13	MaroofRaza	New		-																
Previous Complain History :	<table><thead><tr><th>Date Time</th><th>Technician Name</th><th>Remark</th></tr></thead><tbody><tr><td>26-09-2025 11:16:24</td><td>MaroofRaza</td><td>1 football ground camera working. counselor room camera working admin camera working 401 passage camera faulty power issue bullet camera collect. principle cabin camera reset pending because principle sir working continue.</td></tr><tr><td>16-09-2025 12:15:31</td><td>Prashant Paswan</td><td>513 out side camera pending,707 camera faulty,8th floor material out side camera faulty collect,laberray out side camera 22.09.2025 - Rahul visited - football room camera issue not working/513 room camera installed/707 camera installed/Material room camera not adding to NVR/401 camera cable faulty orange pair/Principle room analog camera issue</td></tr></tbody></table>					Date Time	Technician Name	Remark	26-09-2025 11:16:24	MaroofRaza	1 football ground camera working. counselor room camera working admin camera working 401 passage camera faulty power issue bullet camera collect. principle cabin camera reset pending because principle sir working continue.	16-09-2025 12:15:31	Prashant Paswan	513 out side camera pending,707 camera faulty,8th floor material out side camera faulty collect,laberray out side camera 22.09.2025 - Rahul visited - football room camera issue not working/513 room camera installed/707 camera installed/Material room camera not adding to NVR/401 camera cable faulty orange pair/Principle room analog camera issue						
Date Time	Technician Name	Remark																		
26-09-2025 11:16:24	MaroofRaza	1 football ground camera working. counselor room camera working admin camera working 401 passage camera faulty power issue bullet camera collect. principle cabin camera reset pending because principle sir working continue.																		
16-09-2025 12:15:31	Prashant Paswan	513 out side camera pending,707 camera faulty,8th floor material out side camera faulty collect,laberray out side camera 22.09.2025 - Rahul visited - football room camera issue not working/513 room camera installed/707 camera installed/Material room camera not adding to NVR/401 camera cable faulty orange pair/Principle room analog camera issue																		