Vallabh Enterprises

Regd. Office : 401, shanti kutir, shivaji road, near thakur international school, kandivali(west) mumbai - 400067 Support : | W : www.vallabhenterprises.com E : vallabhsecure@yahoo.co.in

Service Status Details : VE2230 **Priority** : Low **Created By :** Admin - Apurva Vajaria **Complaint Mob.** 9819990297 **No. :** Technician Siddhesh Chavan **Technician Mobile** 8080922985 Name : Complain 18-11-2020 11:03:52 **Ticket Type :** Date & Time : **Vendor Details :** Bhoomi Ganga Customer's Mobile 9819990297 Vipul Bhai Company Name : Name/Client Enclave A Wing Name : **Address** : Mumbai,,,, Maharashtra **AMC Details :** 31-12-2020 12:00:00 Type : Expiry Date : Non-Comprehensive **Product Name :** VDP **Complain**: 501 501 lobby video issue solved and 101 flat to distributer cable issue and 2 camera no video issue Technician solved and play back show to watch man and all working ok **Comment** : Complain Desktop - Apurva Vajaria **Operator** : **Remark** : 501 lobby video issue solved and 101 flat to distributer cable issue and 2 camera no video issue solved and play back show to watch man and all working ok **Status History :** Remark **Date Time Technician Name** Status Sign 18-11-2020 05:01:14 Siddhesh Chavan Completed 501 lobby video issue solved $\langle \lambda \rangle$ and 101 flat to distributer cable issue and 2 camera no video issue solved and play back show to watch man and all working ok 18-11-2020 11:04:24 Siddhesh Chavan New 18-11-2020 11:03:52 Siddhesh Chavan New **Previous Date Time Technician Name** Remark Complain History : 08-12-2020 03:31:14 Parshva Shah 08-12-2020 09:55:07 YogeshDesai lobby panel lock connectors were removed from lobby panel panel was half removed from lobby bracket lobby panel is fixed temporarily for now lock and calls are working properly to all flats